



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|------------|------------------|--|--------------------------|------------------------------------|------|
| PG-ECL-100 | N/A | AS350 BA, B2, B3 | LONGLINE WITH 50 AMP POWER SYSTEM (STANDARD) | 350-900514 | 08-Jun-04 | 2 |
| PG-ECL-101 | N/A | AS350 | PUBLIC ADDRESS / SIREN SYSTEM | | 03-Mar-03 | 0 |
| PG-ECL-102 | N/A | AS350 B3 | RIGHT HAND LITTER KIT INSTALLATION | 350-200144 | Superseded with FMS-ECL-108 | |
| PG-ECL-103 | N/A | EC130 B4 | LONGLINE WITH 50 AMP POWER SYSTEM | 130-900014 | 07-Jul-08 | 2 |
| PG-ECL-104 | N/A | EC130 B4 / T2 | DOOR OPEN WARNING | 130-900104 130-900114 | 12-May-15 | 1 |
| PG-ECL-105 | N/A | EC120 B | LONGLINE WITH 50 AMP POWER. | 120-922034 | 29-Jan-05 | 0 |
| PG-ECL-106 | N/A | AS355 N | LONGLINE WITH 50 AMP POWER SYSTEM | ESK-1353 | 11-May-06 | 0 |
| PG-ECL-107 | N/A | AS350 B2, B3 | LONGLINE WITH 50 AMP POWER SYSTEM | 350-900554 | 22-May-07 | 0 |
| PG-ECL-108 | N/A | AS350 B2 | LONGLINE WITH 50 AMP POWER SYSTEM | 350-900554 (SN Specific) | 03-Aug-07 | 0 |
| PG-ECL-109 | N/A | EC120 | LONGLINE WITH 50 AMP POWER SYSTEM | 120-922034 | 03-Dec-09 | 1 |
| PG-ECL-110 | N/A | AS350 | DOOR OPEN WARNING | 350-900274 | 26-Feb-08 | 0 |
| PG-ECL-111 | N/A | AS355 NP | LONGLINE WITH 50 AMP POWER SYSTEM | 350-900554 (SN Specific) | 08-Aug-08 | 0 |
| PG-ECL-112 | N/A | AS355 NP | LONGLINE WITH 50 AMP POWER SYSTEM | 350-900554 (SN Specific) | 07-Feb-11 | 0 |
| PG-ECL-113 | N/A | AS350 B2, B3 | LONGLINE WITH 50 AMP POWER SYSTEM | 350-900564 | 20-Jan-12 | 0 |

Pilot's Guides

Last Updated: 4 October 2016



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|-----------------------------------|-----------------------------|-------------|-------------|
| PG-ECL-114 | N/A | AS350 B3 | LONGLINE WITH 50 AMP POWER SYSTEM | 350-900954 (SN Specific) | 30-May-13 | 0 |