

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|------------|----------|---|---------------------------|-----------|------|
| ICA-ECL-025 | | AS350 B3 | COMM NAV SYSTEM | 350-870854 | 17-Feb-04 | 0 |
| ICA-ECL-026 | SH00-30 | EC120B | SETTLING PROTECTORS | 120-500214-02 | 19-May-05 | 3 |
| ICA-ECL-029 | | EC120B | COMM NAV SYSTEM STANDARD PACKAGE | | 13-Sep-00 | 1 |
| ICA-ECL-030 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870484 | 13-Sep-00 | 1 |
| ICA-ECL-031 | | EC120B | COMM NAV INSTALLATION, STANDARD PACKAGE | 120-870494 | 13-Sep-00 | 1 |
| ICA-ECL-032 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870444 | 13-Sep-00 | 1 |
| ICA-ECL-033 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870544 | 13-Sep-00 | 1 |
| ICA-ECL-034 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870454, 120-870504 | 13-Sep-00 | 1 |
| ICA-ECL-035 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870654 | 13-Sep-00 | 1 |
| ICA-ECL-036 | | EC120B | COMM NAV INSTALLATION, STANDARD PACKAGE | 120-870404 | 13-Sep-00 | 1 |
| ICA-ECL-037 | | EC120B | DIRECTIONAL GYRO | 120-870274 | 29-Apr-02 | 2 |
| ICA-ECL-038 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870074 | 13-Sep-00 | 1 |
| ICA-ECL-039 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870114 | 13-Sep-00 | 1 |
| ICA-ECL-040 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870094 | 13-Sep-00 | 1 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|------------|--------|--|-------------|-----------|------|
| ICA-ECL-041 | | EC120B | SLASS SYSTEM | | 25-Jun-01 | 0 |
| ICA-ECL-042A | | EC120B | FLIR SYSTEM | 120-901014 | 21-Dec-01 | 4 |
| ICA-ECL-100 | | EC120B | PA/SPEAKER | 120-888414 | 10-Jul-03 | 2 |
| ICA-ECL-101 | | EC120B | GPS NAVIGATION SYSTEM | 120-870894 | 29-Apr-02 | 0 |
| ICA-ECL-102 | | EC120B | BASIC KY-196 VHF COMM 1 VHF TRANSCEIVER SYSTEM | 120-870484 | 29-Apr-02 | 0 |
| ICA-ECL-103 | | EC120B | BASIC AND ENHANCED 4000-10A ELT SYSTEM | 120-870914 | 29-Apr-02 | 0 |
| ICA-ECL-104 | | EC120B | BASIC AND ENHANCED DIGITAL CLOCK | 120-870934 | 29-Apr-02 | 0 |
| ICA-ECL-105 | | EC120B | ENHANCED KT-76C TRANSPONDER SYSTEM | 120-870944 | 29-Apr-02 | 0 |
| ICA-ECL-106 | | EC120B | BASIC KT-76A TRANSPONDER SYSTEM | 120-870454 | 29-Apr-02 | 0 |
| ICA-ECL-107 | | EC120B | BASIC AND ENHANCED 200HM ELT SYSTEM | 120-870924 | 29-Apr-02 | 0 |
| ICA-ECL-108 | | EC120B | COMM/NAV SYSTEM STANDARD PACKAGE TC TYPE CERTIFICATE | | 04-Dec-01 | 0 |
| ICA-ECL-109 | | EC120B | STANDARD PACKAGE, BASIC AND ENHANCED AMS-42 AUDIO SYSTEM | 120-870904 | 02-May-00 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|-----------|--|--|-----------|------|
| ICA-ECL-110 | | EC120B | STANDARD PACKAGE, ENHANCED COMM 1 SYSTEM | 120-870534 | 02-May-02 | 0 |
| ICA-ECL-111 | | EC130 B4 | AFT RH CABIN DOOR RETROFIT | 130-202424 | 10-Jul-03 | 1 |
| ICA-ECL-112 | SH02-38 | EC130 B4 | COWLING MAINTENANCE STEPS | 130-200094/104 | 22-Nov-02 | 0 |
| ICA-ECL-114 | O-LSH02-057 | EC 120B | COMM NAV EQUIPMENT | 120-889654, 120-883174, 120-884774 | 11-Oct-02 | 0 |
| ICA-ECL-116A | O-LSH02-672D | EC120B | FLIR SYSTEM | 120-901064 | 20-Nov-02 | 2 |
| ICA-ECL-117 | SH02-39 | EC120B | IMPROVED HEATING SYSTEM | 120-701014 | 10-May-13 | 7 |
| ICA-ECL-118 | SH02-42 | EC130 B4 | AIRFRAME FUEL FILTER | 130-600004 | 07-Jun-22 | 10 |
| ICA-ECL-119 | SH02-45 | EC130 B4 | LITTER KIT FOR 7 & 8 PLACE | 130-200034 | 09-Jun-05 | 3 |
| ICA-ECL-120 | SH02-44 | EC130 B4 | CARGO PODS | 130-200814 | 30-Dec-02 | 0 |
| ICA-ECL-122 | SH03-15 | EC120B | SPECTROLAB SX-16 NIGHTSUN SEARCHLIGHT | 120-901234 | 20-Mar-06 | 2 |
| ICA-ECL-123 | SH03-33 | EC130 B4 | CARGO POD INSTALLATION | 130-201024 | 11-Apr-13 | 4 |
| ICA-ECL-124 | SH01-22 | AS350/355 | SETTLING PROTECTORS | 120-500214-01 | 19-May-05 | 1 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|------------|------------------------|--------------------------------------|---------------|-----------|------|
| ICA-ECL-125 | SH96-31 | AS350/355 | BATTERY RELOCATION | 350-700324 | 27-Aug-24 | 13 |
| ICA-ECL-126 | SH96-32 | AS350 | RIGHT HAND LITTER KIT | 350-200144 | 10-Mar-17 | 4 |
| ICA-ECL-127 | SH94-29 | AS350/355 | LEFT HAND LITTER KIT | 350-200034 | 11-Jun-20 | 6 |
| ICA-ECL-128 | SH04-28 | EC130 B4 | AFT BENCH SEAT | 130-700614 | 19-Feb-08 | 4 |
| ICA-ECL-129 | SH02-42 | AS350 B3 | AIRFRAME FUEL FILTER | 350-600024 | 07-Jun-22 | 8 |
| ICA-ECL-130 | SH94-31 | AS350 B, BA, B1, B2 | AIRFRAME FUEL FILTER | 350-600004 | 09-Apr-13 | 4 |
| ICA-ECL-131 | SH96-61 | AS350/355 | CARGO MIRROR INSTALLATION | 350-200254/64 | 16-May-18 | 1 |
| ICA-ECL-132 | SH96-114 | AS350 | BELLY-MOUNTED ANTI-COLLISION LIGHT | 350-900624 | 10-Mar-08 | 1 |
| ICA-ECL-133 | SH05-18 | AS350 | HIGH VISIBILITY DOOR (SHORT) | 350-202414 | 18-Apr-13 | 2 |
| ICA-ECL-134 | SH04-53 | EC130 B4 | OPERATION WITH SANDFILTER REMOVED | 130-800034 | 30-Nov-04 | 0 |
| ICA-ECL-136 | SH05-39 | EC130 B4 | WIRE STRIKE PROTECTION SYSTEM | 130-300214 | 12-Mar-24 | 1 |
| ICA-ECL-137 | SH05-47 | EC120B | FLIR U8000/U8500 SYSTEM INSTALLATION | 120-901814 | 04-Dec-08 | 1 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|-------------|-----------|------------------------------------|---------------------------|-----------|------|
| ICA-ECL-138 | O-LSH05-310 | EC120B | VIDEO DOWNLINK SYSTEM | 120-902904 | 19-May-06 | 1 |
| ICA-ECL-139 | SH06-11 | EC130 B4 | HEAVY DUTY BATTERY INSTALLATION | 130-700214 | 20-Mar-06 | 0 |
| ICA-ECL-140 | SH06-12 | AS350/355 | ENLARGED VERTICAL REFERENCE WINDOW | 350/355-201154 | 28-Jan-15 | 5 |
| ICA-ECL-141 | SH97-34 | AS350/355 | FORWARD OPENING REAR CARGO DOOR | 350-201014, 130-201004 | 30-May-13 | 5 |
| ICA-ECL-143 | SH06-28 | AS350 | POP IMAGING SYSTEM | 350-903214 | 15-Jun-07 | 2 |
| ICA-ECL-144 | | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902924 | 19-Feb-06 | 0 |
| ICA-ECL-145 | | AS350 B3 | FLIR U7000 SYSTEM INSTALLATION | 350-903504 | 21-Feb-06 | 0 |
| ICA-ECL-147 | SH07-50 | EC130 B4 | COMM NAV SYSTEM MODIFICATION | 130-883004 | 27-Aug-08 | 2 |
| ICA-ECL-148 | SH07-48 | AS350 B3 | COMM NAV SYSTEM MODIFICATION | 350-880934 | 16-Apr-10 | 3 |
| ICA-ECL-149 | SH05-16 | AS350 B3 | COMM NAV SYSTEM MODIFICATION | 350-880884 | 12-May-08 | 0 |
| ICA-ECL-150 | SH99-205 | AS350 | PUBLIC ADDRESS / SIREN SYSTEM | 350-888594 | 30-Nov-07 | 0 |
| ICA-ECL-152 | O-LSH98-107 | AS350 B3 | SECURITY BARRIER | 350-702014 | 03-Feb-10 | 1 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|-----------|---|-----------------|------------|------|
| ICA-ECL-153 | O-LSH07-020 | AS350 B3 | MISSION EQUIPMENT RACK | 350-902824 | 25-Apr-08 | 0 |
| ICA-ECL-154 | O-LSH07-015 | AS350 B3 | ALTERNATIVE LIGHTING SYSTEM | 350-902524 | 29-Aug-08 | 1 |
| ICA-ECL-155 | O-LSH08-283D | EC120B | ALTERNATE LIGHTING | 120-903214 | 11-Dec-08 | 0 |
| ICA-ECL-156 | O-LSH08-282 | EC120B | VIDEO DOWNLINK SYSTEM | 120-902934 | 12-Dec-08 | 1 |
| ICA-ECL-157 | O-LSH08-288 | AS350 B3 | COMM NAV SYSTEM | 350-880944 | 19-Dec-08 | 0 |
| ICA-ECL-158 | O-LSH08-288 | AS350 B3 | LH PILOT CONFIGURATION | 350-400164 | 15-Jul-09 | 1 |
| ICA-ECL-161 | O-LSH08-288 | AS350 B3 | TWO PLACE FORWARD PASSENGER SEAT | 350-200624 | 19-Dec-08 | 0 |
| ICA-ECL-162 | O-LSH08-298 | EC 130 B4 | DUAL BATTERY INSTALLATION | 350 A62 2537 00 | 17-June-13 | 3 |
| ICA-ECL-163 | | EC120 B | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880204 | 09-Jan-13 | 0 |
| ICA-ECL-164 | O-LSH09-081 | AS350 B2 | COMM NAV SYSTEM | 350-880954 | 21-Apr-09 | 1 |
| ICA-ECL-165 | SH09-11 | AS350 B2 | DUAL SAGEM ICDS-6 INSTALLATION | 350-873044 | 04-Nov-09 | 1 |
| ICA-ECL-166 | O-LSH09-127 | AS350 B2 | INTERIOR | 350-701614 | 27-Apr-09 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|----------|------------------------|------------------------------|-----------|------|
| ICA-ECL-167 | O-LSH09-128 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701624 | 14-Sep-09 | 2 |
| ICA-ECL-168 | SH96-32 | AS350 | LEFT SIDE PILOT | 350-400004/74, 350-400164 | 05-Mar-24 | 8 |
| ICA-ECL-169 | O-LSH09-123 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701614 | 14-Nov-13 | 7 |
| ICA-ECL-170 | O-LSH09-245 | EC120B | DUAL SAGEM ICDS-6A | 120-872744 | 31-Jul-09 | 2 |
| ICA-ECL-171 | O-LSH09-247 | EC120B | COMM NAV SYSTEM | 120-880284 | 31-Jul-09 | 1 |
| ICA-ECL-172 | O-LSH09-142 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701624 | 11-May-09 | 0 |
| ICA-ECL-173 | O-LSH09-141 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701634 | 06-May-09 | 0 |
| ICA-ECL-174 | O-LSH09-145 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701634 | 08-Sep-09 | 1 |
| ICA-ECL-175 | O-LSH09-224D | EC120B | INTERIOR MODIFICATIONS | 120-701614 | 22-Jul-09 | 1 |
| ICA-ECL-177 | O-LSH09-202 | EC120B | INTERIOR MODIFICATIONS | 120-701624 | 25-Jun-09 | 0 |
| ICA-ECL-178 | O-LSH09-263D | AS350 B3 | INTERIOR MODIFICATIONS | 350-701644 | 18-Aug-09 | 1 |
| ICA-ECL-179 | O-LSH09-266D | EC130 B4 | INTERIOR MODIFICATIONS | 130-701644 | 18-Sep-09 | 1 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|----------|------------------------------|-------------|-----------|------|
| ICA-ECL-180 | O-LSH09-264D | AS350 | INTERIOR MODIFICATIONS | 350-701684 | 27-Aug-09 | 0 |
| ICA-ECL-181 | O-LSH09-354 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701664 | 24-Nov-09 | 0 |
| ICA-ECL-182 | O-LSH09-0342 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701654 | 04-Nov-09 | 0 |
| ICA-ECL-183 | O-LSH09-0343 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701674 | 04-Nov-09 | 0 |
| ICA-ECL-184 | O-LSH09-379 | AS350 | INTERIOR MODIFICATIONS | 350-701694 | 07-Dec-09 | 0 |
| ICA-ECL-185 | O-LSH09-355 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701704 | 29-Jul-10 | 1 |
| ICA-ECL-186 | O-LSH10-103 | AS350 | INTERIOR MODIFICATIONS | 350-701714 | 27-Apr-10 | 1 |
| ICA-ECL-187 | O-LSH10-019 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701724 | 25-Jan-10 | 0 |
| ICA-ECL-188 | O-LSH10-104 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701744 | 26-Apr-10 | 0 |
| ICA-ECL-189 | O-LSH10-091 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701754 | 13-Apr-10 | 1 |
| ICA-ECL-190 | O-LSH10-102 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701734 | 14-Jan-11 | 3 |
| ICA-ECL-191 | SH10-20 | EC130 B4 | OPERATION WITH DOORS REMOVED | | 18-Dec-13 | 3 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|-------------|----------|----------------------------------|-------------|-----------|------|
| ICA-ECL-192 | O-LSH10-114 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701654 | 05-May-10 | 0 |
| ICA-ECL-194 | O-LSH10-069 | EC130 B4 | CABIN BACK WALL ATTACHMENT RINGS | 130-203104 | 13-Aug-12 | 1 |
| ICA-ECL-195 | O-LSH10-181 | EC120 | INTERIOR MODIFICATIONS | 120-701634 | 10-Jun-10 | 0 |
| ICA-ECL-196 | O-LSH10-113 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701764 | 05-May-10 | 0 |
| ICA-ECL-197 | O-LSH10-190 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701774 | 24-Jun-10 | 0 |
| ICA-ECL-199 | O-LSH10-203 | EC120B | INTERIOR MODIFICATIONS | 120-701654 | 19-Jul-10 | 0 |
| ICA-ECL-200 | O-LSH10-243 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701664 | 20-Aug-10 | 0 |
| ICA-ECL-201 | SH12-53 | EC130B4 | SECOND BATTERY INSTALLATION | 130-700234 | 01-Oct-12 | 5 |
| ICA-ECL-202 | O-LSH10-259 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701674 | 17-Sep-10 | 0 |
| ICA-ECL-203 | SH12-9 | EC120 | RH DOOR INSTALLATION | 120-200014 | 27-Feb-13 | 1 |
| ICA-ECL-204 | SH12-10 | EC130 B4 | RH DOOR INSTALLATION | 120-200014 | 27-Feb-13 | 1 |
| ICA-ECL-205 | O-LSH10-291 | EC120B | INTERIOR MODIFICATIONS | 120-701644 | 05-Nov-10 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|----------------|-----------|--|-------------|-------------|------|
| ICA-ECL-206 | O-LSH10-308 | EC120B | FLIR U8500 SYSTEM INSTALLATION | 120-901864 | 30-Nov-10 | 2 |
| ICA-ECL-207 | SH97-33 | AS350/355 | REAR CARGO DOOR HINGE AND LATCH MODIFICATION | 350-201064 | 15-Oct-2013 | 2 |
| ICA-ECL-208 | O-LSH10-309 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701794 | 02-Apr-12 | 2 |
| ICA-ECL-209 | SH11-11 | EC135 | CARGO COMPARTMENT MODS | 135-200304 | 13-Apr-11 | 0 |
| ICA-ECL-211 | O-LSH-11-052 | EC135 | INTERIOR MODIFICATIONS | 135-701614 | 04-Apr-11 | 0 |
| ICA-ECL-212 | O-LSH-11-066 | EC135 | FLIR INSTALLATION | 135-901814 | 21-Apr-11 | 0 |
| ICA-ECL-213 | O-LSH-11-065 | EC135 | SX-16 INSTALLATION | 135-901214 | 21-Apr-11 | 0 |
| ICA-ECL-214 | O-LSH-11-070 | EC135 | VIDEO DOWNLINK | 135-902714 | 15-Apr-11 | 0 |
| ICA-ECL-215 | O-LSH-11-069 | EC135 | DOOR OPEN WARNING | 135-901014 | 15-Apr-11 | 0 |
| ICA-ECL-216 | O-LSH-11-073/D | AS350 B2 | COMM NAV SYSTEM | 350-880974 | 20-Apr-11 | 1 |
| ICA-ECL-217 | O-LSH-11-059 | AS355 NP | INTERIOR MODIFICATIONS | 355-701614 | 07-Apr-11 | 0 |
| ICA-ECL-218 | O-LSH-11-053 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701784 | 05-Apr-11 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|----------------|----------|---------------------------|-------------|-----------|------|
| ICA-ECL-219 | O-LSH-11-097 | AS350 B3 | INTERIOR MODIFICATIONS | 350-702234 | 18-May-11 | 1 |
| ICA-ECL-220 | O-LSH-11-087 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701804 | 03-May-11 | 0 |
| ICA-ECL-221 | O-LSH-11-081/D | AS350 B3 | BMS DOWNLINK | 350-902994 | 10-May-11 | 1 |
| ICA-ECL-222 | O-LSH-11-074/D | EC135 | PULSE LIGHT INSTALLATION | 135-902414 | 21-Apr-11 | 1 |
| ICA-ECL-223 | SH11-35 | EC130 B4 | ADJUSTABLE GLARE SHIELD | 130-885114 | 17-Jun-13 | 1 |
| ICA-ECL-225 | O-LSH-11-064/D | EC130 B4 | INTERIOR MODIFICATIONS | 130-701684 | 19-Apr-11 | 0 |
| ICA-ECL-227 | O-LSH-11-091/D | AS350 B2 | INTERIOR MODIFICATIONS | 350-702244 | 10-May-11 | 0 |
| ICA-ECL-228 | O-LSH-11-073/D | AS350 B3 | INTERIOR MODIFICATIONS | 350-701034 | 20-May-11 | 0 |
| ICA-ECL-229 | O-LSH-11-124 | AS350 B3 | INTERIOR MODIFICATIONS | 350-702254 | 30-Jun-11 | 0 |
| ICA-ECL-230 | O-LSH-11-134 | AS350 B2 | INTERIOR MODIFICATIONS | 350-702224 | 15-Jul-11 | 1 |
| ICA-ECL-232 | O-LSH-11-127 | AS350 B2 | INTERIOR MODIFICATIONS | 350-702264 | 06-Jul-11 | 1 |
| ICA-ECL-233 | SH12-52 | AS350 | CABLE CUTTER INSTALLATION | 350-252004 | 05-Dec-14 | 3 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|---------------------|----------------------------------|--|-----------|------|
| ICA-ECL-234 | O-LSH11-111 | AS350B3 | ADJUSTABLE GLARE SHIELD | ESK-1457 | 17-Jun-11 | 0 |
| ICA-ECL-235 | SH98-43 | AS350/355 | REAR CROSS TUBE MAINTENANCE STEP | 350-500604 | 11-Dec-14 | 1 |
| ICA-ECL-236 | O-LSH11-172 | AS350 B3 | INTERIOR MODIFICATION | 350-702274 | 03-Oct-11 | 0 |
| ICA-ECL-237 | SH96-126 | AS350/355/ EC130 | BLADE TIE DOWN PROVISIONS | 350-700414/ 130-700414 | 12-May-15 | 2 |
| ICA-ECL-238 | O-LSH11-167 | AS350 B3 | INTERIOR MODIFICATION | 350-702284 | 26-Sep-11 | 0 |
| ICA-ECL-241 | O-LSH11-220 | EC130 B4 | INTERIOR MODIFICATION | 130-701694 | 08-Dec-11 | 0 |
| ICA-ECL-242 | SH12-28 | AS350 / 355 | STANDARD INTERIOR MODIFICATION | 350-701904 | 05-Aug-22 | 6 |
| ICA-ECL-243 | SH12-28 | AS350 / 355 | STANDARD INTERIOR MODIFICATION | 350-701814 | 11-Nov-14 | 2 |
| ICA-ECL-244 | SH12-28 | AS350 / 355 | STANDARD INTERIOR MODIFICATION | 350-701074, 350-702104, 350-702124 | 21-Mar-18 | 3 |
| ICA-ECL-245 | SH12-28 | AS350 / 355 | STANDARD INTERIOR MODIFICATION | 350-701044 | 13-Sep-24 | 5 |
| ICA-ECL-246 | O-LSH12-010 | AS350 B3 | INTERIOR MODIFICATION | 350-702314 | 20-Jan-12 | 0 |
| ICA-ECL-247 | O-LSH12-033/D | AS350 B3 | INTERIOR MODIFICATION | 350-702294 | 09-Mar-12 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|-------------|--------------|---------------------------------------|-------------|-----------|------|
| ICA-ECL-248 | O-LSH12-046 | AS350 B2 | INTERIOR MODIFICATION | 350-702334 | 08-Mar-12 | 1 |
| ICA-ECL-249 | O-LSH12-054 | AS350 B3 | INTERIOR MODIFICATION | 350-702304 | 21-Mar-12 | 1 |
| ICA-ECL-250 | SH12-12 | EC130 | REAR DRIVE SHAFT END CAP INSTALLATION | 130-300014 | 09-Jul-14 | 1 |
| ICA-ECL-251 | SH12-16 | AS350 B3 | OPERATION WITH SANDFILTER REMOVED | 350-800044 | 13-Mar-12 | 2 |
| ICA-ECL-252 | O-LSH12-079 | AS350 B3 | INTERIOR MODIFICATION | 350-702324 | 24-Apr-12 | 0 |
| ICA-ECL-253 | O-LSH12-086 | AS350 B3 | INTERIOR MODIFICATION | 350-702354 | 14-May-12 | 1 |
| ICA-AHCA-254 | SH14-10 | AS350 B2, B3 | LONGLINE ELECTRICAL PROVISIONS | 350-900564 | 29-Apr-15 | 3 |
| ICA-ECL-255 | O-LSH12-189 | AS350 B3 | COMM NAV SYSTEM | 350-881014 | 10-Dec-12 | 0 |
| ICA-ECL-256 | O-LSH12-096 | EC130 B4 | INTERIOR MODIFICATION | 130-701714 | 22-May-12 | 1 |
| ICA-ECL-257 | O-LSH12-099 | EC130 B4 | INTERIOR MODIFICATION | 130-701704 | 25-May-12 | 1 |
| ICA-ECL-258 | O-LSH12-126 | AS350 B3 | INTERIOR MODIFICATION | 350-702384 | 18-Jun-12 | 1 |
| ICA-ECL-259 | SH12-28 | AS350 / 355 | STANDARD INTERIOR MODIFICATION | 350-702204 | 11-Nov-14 | 2 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|---------------------|----------------------------------|-------------|-----------|------|
| ICA-ECL-260 | SH96-39 | AS350 BA, B2, B3 | TWO PLACE FORWARD PASSENGER SEAT | 350-200624 | 18-Dec-13 | 2 |
| ICA-ECL-261 | O-LSH12-177 | AS350 B3e | INTERIOR MODIFICATION | 350-702364 | 01-Nov-12 | 1 |
| ICA-ECL-262 | O-LSH12-168/D | AS350 B2 | INTERIOR MODIFICATION | 350-702344 | 31-Oct-12 | 0 |
| ICA-ECL-266 | O-LSH13-041 | AS350 B2 | INTERIOR MODIFICATION | 350-702374 | 21-Mar-13 | 0 |
| ICA-ECL-267 | O-LSH13-038 | EC130 B4 | INTERIOR MODIFICATION | 130-701724 | 15-Mar-13 | 1 |
| ICA-ECL-268 | O-LSH13-123 | EC135 | INTERIOR MODIFICATION | 135-701624 | 29-Aug-13 | 0 |
| ICA-AHCA-269 | SH20-44 | EC130 T2 | AIRFRAME-MOUNTED FUEL FILTER | 130-600204 | 28-Oct-20 | 1 |
| ICA-ECL-270 | SH14-11 | AS350 / EC130 | FIRE EXTINGUISHER RELOCATION | 130-700014 | 28-Mar-14 | 1 |
| ICA-ECL-271 | O-LSH13-150 | EC120 B | INTERIOR MODIFICATION | 120-701664 | 21-Nov-13 | 1 |
| ICA-ECL-272 | O-LSH13-161 | EC135 | INTERIOR MODIFICATION | 135-701634 | 12-Dec-13 | 1 |
| ICA-AHCA-273 | SH14-31 | EC130 T2 | CARGO PODS | 130-201214 | 27-Jul-23 | 2 |
| ICA-AHCA-274 | SH14-40 | EC130 T2 | CARGO MIRRORS | 130-201414 | 19-Dec-14 | 3 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|-------------------------|--------------|---|--|-----------|------|
| ICA-AHCA-275 | SH14-13 | EC130B4 / T2 | STANDARD INTERIOR MODIFICATION | 130-701904 130-701914 130-701924 | 11-Sep-23 | 1 |
| ICA-AHCA-276 | SH14-13 | EC130B4 / T2 | STANDARD INTERIOR MODIFICATION | 130-701814 | 11-Sep-23 | 1 |
| ICA-AHCA-277 | O-LSH14-072/D | EC130 T2 | INTERIOR MODIFICATION | 130-701734 | 25-Jun-14 | 0 |
| ICA-AHCA-278 | SH14-20 | EC135 | STANDARD INTERIOR MODIFICATION | 135-701644 | 26-May-14 | 0 |
| ICA-AHCA-279 | SH97-60 | AS355 | CARGO PODS LH/RH INSTALLATION | 355-200814/24 | 18-Oct-19 | 1 |
| ICA-AHCA-280 | O-LSH14-148/D SH15-2 | AS355 NP | LEAD ACID BATTERY | 355-700024 | 12-Jun-15 | 1 |
| ICA-AHCA-281 | O-LSH14-150/D | AS355 NP | LONGLINE CONTROL SYSTEM | 355-900034 | 12-Dec-14 | 0 |
| ICA-AHCA-282 | O-LSH14-147/D | AS355 NP | FLIGHT FOLLOWING SATPHONE | 355-903014 | 12-Dec-14 | 0 |
| ICA-AHCA-283 | O-LSH14-149/D | AS355 NP | PULSE LIGHT INSTALLATION | 355-902414 | 12-Dec-14 | 0 |
| ICA-AHCA-284 | O-LSH14-089/D | AS350 B2 | INTERIOR MODIFICATION | 350-702394 | 08-Aug-14 | 0 |
| ICA-AHCA-286 | SH15-7 | AS 355 N, NP | INSTALLATION OF HIGH VISIBILITY FORWARD CABIN DOORS | 350-202014 | 04-May-15 | 0 |
| ICA-AHCA-287 | O-LSH14-138/D | AS355 NP | COMM NAV SYSTEMS | 355-880054 | 12-Dec-14 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|---------------------|--|---------------|-----------|------|
| ICA-AHCA-288 | O-LSH14-120/D | EC130 B4 | INTERIOR MODIFICATION | 130-701754 | 25-Nov-14 | 0 |
| ICA-AHCA-289 | O-LSH15-011/D | EC130 T2 | INTERIOR MODIFICATION | 130-701744 | 06-Mar-15 | 0 |
| ICA-AHCA-290 | O-LSH15-022 | AS350 | FIRE EXTINGUISHER RELOCATION | 350-702074 | 13-Mar-15 | 0 |
| ICA-AHCA-291 | O-LSH15-032/D | EC130 T2 | INTERIOR MODIFICATION | 130-701824 | 12-May-15 | 0 |
| ICA-AHCA-292 | SH15-48 | EC130 T2 | 50 AMP / LONGLINE / CAROUSEL SYSTEM | 130-900024 | 23-Oct-15 | 0 |
| ICA-AHCA-293 | O-LSH15-112/D | EC130 T2 | GARMIN G500H DEVIATIONS TO FAA STC SR09497RC-D | 130-950304 | 06-Oct-15 | 0 |
| ICA-AHCA-294 | SH97-15 | AS 350 | INSTALLATION OF LH and/or RH CARGO PODS | 350-201814/24 | 12-Mar-24 | 3 |
| ICA-AHCA-295 | SH16-14 | EC135 | REMOVABLE DOOR PINS | 135-201014 | 11-Mar-16 | 0 |
| ICA-AHCA-296 | SH16-11 | AS350 / EC130 | PROVISIONS, ENGINE AIR INTAKE COVER | 350-700924 | 04-Mar-16 | 0 |
| ICA-AHCA-297 | SH21-25 | AS 350 B3 | AIRFRAME MOUNTED FUEL FILTER WITH CRFS | 350-600044 | 06-Mar-23 | 1 |
| ICA-AHCA-298 | SH17-47 | BK117 C-2, D-2, D-3 | INSTALLATION OF REMOVABLE PINS FOR HINGED DOOR | 145-201014 | 30-Sep-21 | 1 |
| ICA-AHCA-299 | O-LSH19-060/D | EC 130 T2 | HEAVY DUTY BATTERY INSTALLATION | 130-700244 | 06-Jun-19 | 1 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|--------------------------|---|--|-----------|------|
| ICA-AHCA-300 | O-LSH18-051 | AS 350 B3 | SEAT COVERS MODIFICATIONS | 350-702444 | 19-Apr-19 | 0 |
| ICA-AHCA-301 | SH14-13 | EC130B4 / T2 | STANDARD INTERIOR MODIFICATION | 350-701074 350-702104 350-702124 | 11-Sep-23 | 0 |
| ICA-AHCA-302 | O-LSH18-077/D | AS 350 B3 | SEAT COVERS MODIFICATIONS | 350-702454 | 11-Jun-18 | 0 |
| ICA-AHCA-303 | SH18-56 | AS 350 B3 / EC 130 T2 | ALTERNATE STANDBY ALTIMETER | 350-957264 | 09-Oct-18 | 0 |
| ICA-AHCA-304 | O-LSH18-167 | BK 117 D-2 | FLOOR COVERS | 145-701614 | 29-Nov-18 | 0 |
| ICA-AHCA-305 | SH18-67 | BK 117 D-2 | MICROWAVE DOWNLINK SYSTEM | 145-902714 | 28-Nov-18 | 0 |
| ICA-AHCA-306 | O-LSH18-170 | BK 117 D-2 | SEAT COVERS MODIFICATIONS | 145-701634 | 11-Dec-18 | 0 |
| ICA-AHCA-307 | O-LSH19-061/D | EC 130 T2 | GARMIN GTS-800 TRAFFIC ADVISORY SYSTEM INSTALLATION | 130-870514 | 06-Jun-19 | 1 |
| ICA-AHCA-308 | O-LSH19-065/D | EC 130 T2 | INTERIOR MODIFICATIONS | 130-701784 | 04-Apr-18 | 0 |
| ICA-AHCA-310 | SH19-56 | EC 130 T2 | HEAVY DUTY BATTERY INSTALLATION | 130-700244 | 16-Dec-19 | 0 |
| ICA-AHCA-311 | SH19-32 | BK117 D-2 | SUPPLEMENTAL CABIN HEATER INSTALLATION | 145-900004 145-910004 | 25-Oct-21 | 1 |
| ICA-AHCA-312 | SH00-1 | AS 350 | INSTALLATION OF HIGH VISIBILITY MAIN & AFT CABIN DOORS | 350-202014 | 23-Mar-21 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|-------------------|---|--|-----------|------|
| ICA-AHCA-313 | O-LSH19-194/D | AS 350 B3 | SEAT COVERS MODIFICATIONS | 350-702474 | 20-Dec-19 | 0 |
| ICA-AHCA-314 | SH20-47 | BK117 D-2 | ROTOR DISK LIGHTING INSTALLATION | 145-900634 | 5-Jul-21 | 1 |
| ICA-AHCA-315 | SH20-49 | BK117 D-2, D-3 | CABIN HEAT OUTLETS CONTROL | 145-702104 | 16-Dec-21 | 3 |
| ICA-AHCA-316 | O-LSH21-041/D | AS 350 B3 | INTERIOR MODIFICATION | 350-702484 | 30-Apr-21 | 0 |
| ICA-AHCA-317 | SH21-7 | AS 350 B3 | SEAT COVERS MODIFICATIONS | 350-702494 | 26-Feb-21 | 0 |
| ICA-AHCA-319 | SH21-22 | BK117 D-2, D-3 | TECHNISONIC TACTICAL RADIO INSTALLATION | 145-900104 145-900114 160-251014 160-251024 160-251034 | 18-May-21 | 0 |
| ICA-AHCA-320 | N/A | H160 | WIPS | 160-251044 160-252014 160-252024 160-252034 160-252044 | 23-Feb-22 | 0 |
| ICA-AHCA-321 | O-LSH22-154/D | AS 350 B3 | ANCILLARY AIRSPEED INDICATOR INSTALLATION | 350-957314 | 19-Dec-22 | 0 |
| ICA-AHCA-322 | O-LSH23-020 | AS 350 B3 | INTERIOR MODIFICATIONS | 350-702594 | 13-Feb-23 | 0 |
| C320I0190680 | SH24-19 | EC 120 B | INSTALLATION OF SKID SHOES | C320I0190001 | 28-Jun-24 | 0 |
| G250I0146550 | O-LSH23-079 | EC 130 T2 | INTERIOR MODIFICATIONS | G250I0146100 | 28-Jun-23 | 0 |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025

AIRBUS

| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|------------|--|------------------------------|-----------|------|
| G340I0157570 | O-LSH23-098/D | EC 130 T2 | GTS 800 TRAFFIC ADVISORY SYSTEM INSTALLATION | G340I0157100 | 14-Aug-23 | 0 |
| H310I0153550 | SH23-27 | AS 350 B3 | OPTIMIZED INSTRUMENT PANEL INSTALLATION | H310I0153101 H310I0153102 | 27-Oct-23 | 0 |
| H340I0183680 | O-LSH23-126D | AS 350 B3 | INSTRUMENT PANEL MODIFICATIONS INSTALLATION | H340I0183101 | 25-Oct-23 | 0 |
| H430I0307680 | SH24-30 | AS 350 B3 | SINGLE OR DUAL VHF-FM RADIO INSTALL | H430I0307001 H430I0307002 | 26-Nov-24 | 0 |
| L250I0223680 | 8110 | EC 135 P3H | INTERIOR MODIFICATIONS | L250I0223100 | 30-Apr-24 | A |

Instructions for Continued Airworthiness

Last updated: Jan 6, 2025