



| Report Number | STC Number | Model            | Report Title                                 | Part Number              | Date                               | Rev. |
|---------------|------------|------------------|--|--------------------------|------------------------------------|------|
| PG-ECL-100    | N/A        | AS350 BA, B2, B3 | LONGLINE WITH 50 AMP POWER SYSTEM (STANDARD) | 350-900514               | 08-Jun-04                          | 2    |
| PG-ECL-101    | N/A        | AS350            | PUBLIC ADDRESS / SIREN SYSTEM                |                          | 03-Mar-03                          | 0    |
| PG-ECL-102    | N/A        | AS350 B3         | RIGHT HAND LITTER KIT INSTALLATION           | 350-200144               | <b>Superseded with FMS-ECL-108</b> |      |
| PG-ECL-103    | N/A        | EC130 B4         | LONGLINE WITH 50 AMP POWER SYSTEM            | 130-900014               | 07-Jul-08                          | 2    |
| PG-ECL-104    | N/A        | EC130 B4 / T2    | DOOR OPEN WARNING                            | 130-900104<br>130-900114 | 12-May-15                          | 1    |
| PG-ECL-105    | N/A        | EC120 B          | LONGLINE WITH 50 AMP POWER.                  | 120-922034               | 29-Jan-05                          | 0    |
| PG-ECL-106    | N/A        | AS355 N          | LONGLINE WITH 50 AMP POWER SYSTEM            | ESK-1353                 | 11-May-06                          | 0    |
| PG-ECL-107    | N/A        | AS350 B2, B3     | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554               | 22-May-07                          | 0    |
| PG-ECL-108    | N/A        | AS350 B2         | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554 (SN Specific) | 03-Aug-07                          | 0    |
| PG-ECL-109    | N/A        | EC120            | LONGLINE WITH 50 AMP POWER SYSTEM            | 120-922034               | 03-Dec-09                          | 1    |
| PG-ECL-110    | N/A        | AS350 / 355      | DOOR OPEN WARNING                            | 350-900274<br>355-900304 | 30-Sep-21                          | 1    |
| PG-ECL-111    | N/A        | AS355 NP         | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554 (SN Specific) | 08-Aug-08                          | 0    |
| PG-ECL-112    | N/A        | AS355 NP         | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554 (SN Specific) | 07-Feb-11                          | 0    |
| PG-ECL-113    | N/A        | AS350 B2, B3     | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900564               | 20-Jan-12                          | 0    |

Pilot's Guides

Last Updated: Jan 3, 2023



| Report Number   | STC Number | Model     | Report Title                         | Part Number   | Date      | Rev. |
|-----------------|------------|-----------|--------------------------------------|---|-----------|------|
| PG-ECL-114      | N/A        | AS350 B3  | LONGLINE WITH 50 AMP POWER SYSTEM    | 350-900954<br>(SN Specific)                             | 30-May-13 | 0    |
| PG-AHCA-11<br>5 | N/A        | AS350 B3  | LONGLINE WITH 50 AMP POWER SYSTEM    | 350-900974<br>350-900984<br>350-900994<br>(SN Specific) | 17-May-18 | 0    |
| PG-AHCA-11<br>6 | N/A        | BK117 D-2 | MAIN ROTOR FLOOD LIGHTS INSTALLATION | 145-900634  | 24-Jun-19 | 0    |
| PG-AHCA-11<br>7 | N/A        | BK117 D-3 | 115 V AC STATIC INVERTER             | 145-901264  | 02-May-22 | 0    |