



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|----------------------|----------------|--|-------------|-----------|------|
| SIN-ECL-103 | SH02-42 SR01632NY | AS 350 B3 | SAFETY INFORMATION NOTICE - AIRFRAME MOUNTED FUEL FILTER | 350-600024 | 14-Nov-11 | 0 |
| SIN-AHCA-106 | SH06-12 SR03771NY | AS 350, AS 355 | REMINDER OF APPROVAL CONFIGURATION - EVRW | | 21-Sep-20 | 0 |
| SB BO 105 LS 60-5 | | BO 105 LS A-3 | REPLACEMENT OF HOSE | | 13-Mar-07 | |
| SB BO 105 LS 60-6 | | BO 105 LS A-3 | REMOVAL OF N2 OVERSPEED CONTROL SYSTEM | | 13-Mar-07 | |
| SB BO 105 LS 60-7 | | BO 105 LS A-3 | REPLACEMENT OF FUEL FILTER | | 31-Mar-05 | |
| SB/ASB-10 | | BO 105 LS A-3 | SB/ASB INDEX - CHAPTER 10 | | 20-Sep-99 | |
| SB/ASB-20 | | BO 105 LS A-3 | SB/ASB INDEX - CHAPTER 20 | | 20-Sep-99 | |
| SB/ASB-30 | | BO105 LS | SB/ASB INDEX - CHAPTER 30 | | 20-Sep-99 | |
| SB/ASB-40 | | BO105 LS | SB/ASB INDEX - CHAPTER 40 | | 20-Sep-99 | |
| SB/ASB-50 | | BO105 LS | SB/ASB INDEX - CHAPTER 50 | | 20-Sep-99 | |
| SB/ASB-60 | | BO105 LS | SB/ASB INDEX - CHAPTER 60 | | 20-Sep-99 | |
| SB/ASB-70 | | BO105 LS | SB/ASB INDEX - CHAPTER 70 | | 20-Sep-99 | |
| SB/ASB-80 | | BO105 LS | SB/ASB INDEX - CHAPTER 80 | | 20-Sep-99 | |

Service Bulletins, Service Information

Last Updated: 4 January 2022



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|-----------------------|---------------------------------------|---------------------------------|---|--------------------------------|-----------|------|
| SB/ASB-90 | | BO105 LS | SB/ASB INDEX - CHAPTER 90 | | 20-Sep-99 | |
| SB105LS-70-4 | | BO 105 LS A-3 | (BO105 S.B. BINDER) STANDARD EQUT REPLACEMENT OF THE SAFETY HARNESS | | 17-Aug-00 | |
| SB-BO 105 LS 30-10 | | BO 105 LS A-3 | TAIL ROTOR - MODIFICATION OF THE TAIL ROTOR HEAD | | 19-May-05 | |
| SB-BO 105 LS 40-10 | | BO 105 LS A-3 | FLIGHT CONTROLS | | 11-May-09 | |
| SB-BO 105 LS 80-32 | | BO 105 LS A-3 | OPTIONAL EQUIPMENT, CARGO HOOK | | 06-May-09 | |
| SB-BO 105 LS-80-11 | | BO105 LS | (BO105 S.B. BINDER) RETROFIT OF FUEL FLOW/AIR DATA COMPUTER DISPLAY | | 02-Jun-98 | |
| SB-BO 105 LS-80-12 | | BO105 LS | (BO105 S. B. BINDER) OPT-ALLIED SIGNAL MST- 67A MODE S TRANSPONDER | | 08-Jun-98 | |
| SB-BO 105 LS-80-13 | | BO105 LS | (BO105 BINDER) RETROFIT OF WIRE STRIKE PTROTECT. SYST., UPPER CUTTER | | 17-Jun-98 | |
| SB-ECL-98- 76-002 | SH96-32 SR00429NY | AS 350 B2, AS 350 BA | LEFT SIDE PILOT CONFIGURATION | 350-400004 | 27-Jan-00 | 2 |
| SB-ECL-99- 24-02 | SH96-31 SR00422NY | AS 350, AS 355 | BACKING PLATE AND STIFFNER RETROFIT ON BATTERY RELOCATION | 350-790014 | 17-Aug-00 | 1 |
| SB-ECL-99- 24-03 | | AS 350, AS 355 | OPTIONAL RETROFIT OF CARGO POD LATCH COVERS | 350-200834.80 350-200834.85 | 27-Jul-99 | 0 |
| SB-ECL-99- 67-002 | SH96-32 | AS 350, AS 350 B2, AS 350 BA | COLLECTIVE LEVER LOCKING DEVICE | 350-400144 | 29-Sep-99 | 2 |
| SB-ECL-00- 52-001 | SH00-1 SR1107NY | AS 350 | HIGH VIS DOOR GUIDE ASSY INSTL. | 350-202034 350-202044 | 15-Dec-00 | 1 |
| SB-ECL-001A | SN 1002, 1022, 1033, 1028, 1055 | EC 120 B | N.A.T. AUDIO SYSTEM POWER SOURCE, | | 11-Apr-00 | 0 |



| Report Number | STC / SN Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---|---------------|-------------------------------|--|-----------|------|
| SB-ECL-101 | SN 3285 | AS 350 B3 | MODIFICATION OF HEATING INPUT | 350-870034 350-870285 350-870334 | 28-Jan-02 | 0 |
| SB-ECL-102 | SN 3369, SN 3347 SN 3285 | AS 350 B2, B3 | ELT SYSTEM INSTALLATION CHECK | 350-870904 350-870714 350-870404 | 11-Mar-02 | 0 |
| SB-ECL-103 | SH00-1 SR01107NY | AS 350 | HIGH VISIBILITY DOORS | 350-202014 | 31-May-02 | 0 |
| SB-ECL-104 | SH00-1 SR01107NY | AS 350 | HIGH VISIBILITY DOORS | 350-202034 350-202044 | 31-Jul-03 | 0 |
| SB-ECL-105 | SH94-29 SR00407NY | AS 350 | LEFT-HAND LITTER KIT | 350-200174 | 17-Jul-03 | 0 |
| SB-ECL-106 | SH96-62 SR00458NY | AS 350 | RIGHT HAND LITTER KIT | 350-200174 | 28-Jun-04 | 0 |
| SB-ECL-107 | SH02-39 SR01892NY | EC 120 B | IMPROVED HEATING SYSTEM | 120-701014 | 30-Jun-04 | 0 |
| SB-ECL-108 | SH02-42 Issue 1-3 SR01632 dated Mar 18 2003 or earlier | EC 130 B4 | AIRFRAME-MOUNTED FUEL FILTER | 130-600004 | 18-Feb-05 | 4 |
| SB-ECL-109 | SH94-31 Issues 5-7 SR00379NY dated Mar 15 2004 or earlier | AS 350 B3 | AIRFRAME-MOUNTED FUEL FILTER | 350-600004 | 14-Jul-06 | 5 |
| SB-ECL-110 | O-LSH04-138 | EC 130 B4 | FM SYSTEM INTERLOCK DIODE | 350-870084 | 07-Oct-04 | 0 |
| SB-ECL-111 | | EC 120 B | FM SYSTEM INTERLOCK DIODE | 350-870404 | 07-Oct-04 | 0 |

Service Bulletins, Service Information

Last Updated: 4 January 2022



| Report Number | STC / SN Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---|-------------------|-------------------------------------|--|-----------|------|
| SB-ECL-112 | | AS 350 B2, B3 | FM SYSTEM INTERLOCK DIODE | 350-878564 | 07-Oct-04 | 0 |
| SB-ECL-113 | SH96-31 Issue 5 or earlier SR00422NY dated May 30 2002 or earlier | AS 350 | BATTERY RELOCATION FUSE REPLACEMENT | 350-700214 350-700324 | 19-May-05 | 1 |
| SB-ECL-114 | SN 3139 SN 3072/3072 SN 3142 | AS 350 B3 | AUDIO SYSTEM MODIFICATIONS | 350-879354 350-879444 350-878854 | 11-Nov-04 | 0 |
| SB-ECL-115 | SN 2051 to 2054 | BO 105 LS A-3 | AUDIO LOW ROTOR WARNING | 105-881594 | 14-Jan-05 | 0 |
| SB-ECL-116 | SH05-39 | EC 130 B4 | WIRE STRIKE PROTECTION SYSTEM | 130-200214 | 13-Jan-06 | 0 |
| SB-ECL-117 | SN 1355 | EC 120 B | SATELLITE PHONE | 120-901704 | 22-Feb-07 | 0 |
| SB-ECL-118 | SH02-42 SR01632NY SH91-31 SR00379NY | AS 350 B3 | AIRFRAME FUEL FILTER INSTALLTION | 350-600024 350-600004 | 03-Apr-08 | 1 |
| SB-ECL-119 | SH02-42 SR01632NY | EC 130 B4 | AIRFRAME FUEL FILTER INSTALLTION | 130-600004 | 04-Jul-07 | 0 |
| SB-ECL-120 | SH04-28 Issue 2 or earlier | EC 130 B4 | AFT BENCH SEAT ASSEMBLY | 130-700614 | 20-Aug-12 | 1 |
| SB-ECL-121 | SH04-28 Issue 3 or earlier | EC 130 B4 | AFT BENCH SEAT ASSEMBLY | 130-700614 | 19-Feb-08 | 1 |
| SB-ECL-122 | SH96-32 Issue 7 or earlier SR00429NY dated Apr 29 1996 or earlier | AS 350 BA, B2, B3 | LEFT HAND PILOT CONFIGURATION | 350-400004 350-400074 350-400164 | 21-Sep-09 | 1 |

Service Bulletins, Service Information

Last Updated: 4 January 2022



| Report Number | STC / SN Number | Model | Report Title | Part Number | Date | Rev. |
|-----------------|---|------------------------|---|--|-----------|------|
| SB-AHCA-130 | SH96-31 SR00422NY SR00800NY | AS 350, AS 355 | BATTERY RELOCATION, INSPECT SCREW LENGTH | 350-700324 355-700324 | 27-Aug-19 | 0 |
| SB-AHCA-131 | SH00-1 SR01107NY SH05-18 SR02141NY SH15-7 | AS 350, AS 355 | ALTERNATE DOOR LOCK FOR AHCA HIGH VISIBILITY DOORS | 350-202014 350-202414 355-202014 | 25-Jul-19 | 0 |
| SB-AHCA-133 | SH17-47 SR04119NY | MBB-BK 117 C-2, D-2 | INSTALLATION OF REMOVABLE DOOR PINS | 135-201034 135-201014.11 | 11-Nov-21 | 1 |
| SI-BO 105 LS-27 | | BO105 LS | SI-BO 105 LS-27 | | 03-Dec-03 | |
| SI-BO 105 LS-24 | | BO105 LS | SERVICE INFORMATION | | 28-Aug-01 | |
| SI-BO 105 LS-29 | | BO 105 LS A-3 | SERVICE INFORMATION | | 17-Feb-04 | |
| SI-BO 105 LS-38 | | BO 105 LS A-3 | LETTER FROM AIR CRUISERS | | 13-Mar-07 | |
| SI-BO 105 LS-43 | | BO 105 LS A-3 | SERVICE INFORMATION LETTER SIL-TIM-07-012 & -014 | | 03-Apr-08 | |
| SI-BO 105 LS-45 | | BO105 LS | INSTALL OF STCS W/ EUROCOPTER HOLDS NO RESPONSIBILITY | | 27-Aug-08 | |
| SI-BO 105 LS-47 | | BO 105 LS A-3 | NEW PART NUMBER DUE TO VENDOR DISCONTINUATION | | 14-Apr-09 | |
| SI-BO 105-LS-20 | | BO 105 LS A-3 | SX-16 | | 24-May-06 | |



| Report Number | STC / SN Number | Model | Report Title | Part Number | Date | Rev. |
|------------------|---|---|---|------------------|-----------|------|
| SI-BO-105-LS-21 | | BO105 LS | (BO 105 S.B. BINDER) Y2K INFORMATION | | 22-Nov-99 | |
| SI-BO-105-LS-22 | | BO105 LS | (BO 105 S.B. BINDER) ALERT SERVICE INFORMATION | | 30-Mar-00 | |
| SI-BO-105LS-25 | | BO105 LS | ALLIED SIGNAL INSTALLATION BULLETIN | | 07-May-02 | |
| SI-ECL-97-00-02 | | AS 350 | LEFT SIDE PILOT CONFIGURATION | SB-ECL-98-76-002 | 02-Jun-99 | 0 |
| SI-ECL-99-00-01 | | AS 350 | LEFT SIDE PILOT CONFIGURATION | SB-ECL-98-76-002 | 02-Jun-99 | 0 |
| SI-ECL-00-25-001 | SH97-60 SH91-36 SR00795NY SH7000SW-D | AS 355 | COMPATIBILITY BETWEEN ECL CARGO PODS AND AEC SFIM | 355-200814/24 | 15-Dec-00 | 0 |
| SI-ECL-001 | SH02-39 SR01892NY | EC 120 B | IMPROVED HEATING SYSTEM | FMS-ECL-102 | 21-Sep-05 | 1 |
| SI-ECL-002 | SH02-42 SR01632NY | AS 350 B3 | AIRFRAME FUEL FILTER | 350-600024 | 04-Aug-06 | 0 |
| SI-ECL-003 | SH02-42 SR01632NY | EC 130 B4 | AIRFRAME FUEL FILTER | 130-600004 | 04-Aug-06 | 0 |
| SI-ECL-004 | SN 3636, 3683, 3796, 3923 | AS 350 B3 | RYAN TCAD SYSTEM | 350-871474 Rev B | 21-Jun-06 | 0 |
| SI-ECL-005 | SN 1355 | EC 120 B | RYAN TCAD SYSTEM | 120-871294 Rev C | 22-Jun-06 | 0 |
| SI-ECL-006 | | AS 350 B2 w/VEMD, AS 350 B3, EC 120, EC 130 | AURAL WARNING SIGNALS | | 28-Mar-08 | 0 |
| SI-ECL-007 | SH87-9 | BO 105S CDN-BS | BLEED AIR HEATER | 105S-810214 | 14-Apr-09 | 0 |

Service Bulletins, Service Information

Last Updated: 4 January 2022



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|------------------------|---|-------------------|--|--|-----------|------|
| SI-ECL-008 | SH96-32 O-LSH96-0314 O-LSH97-091 O-LSH08-288 SR00429NY SR00525NY | AS 350 BA, B2, B3 | COLLECTIVE LOCK SYSTEM | FMS-ECL-9 MMS-ECL-36 | 19-Jun-09 | 0 |
| SI-ECL-009 | SH96-31 SR00422NY | AS 350, AS 355 | BATTERY RELOCATION | 350-700324.76 | 25-Jun-10 | 0 |
| SI-ECL-010 | SH96-31 SR00422NY SR00800NY | AS 350, AS 355 | BATTERY RELOCATION | 350-700324.77 | 25-Jun-10 | 0 |
| SI-ECL-101 | SH96-32 SR00429NY | AS 350 | CARGO SWING INSTALLATION | 350-400004, 350-400074, 350-400164 | 26-Feb-02 | 0 |
| ASB40-8 | | BO105 LS | HYDRAULIC-FUNCTION TEST OF SOLENOID VALVE | | 15-Apr-96 | 0 |
| ASB-BO 105 LS 30-8 | | BO105 LS | TAIL UNIT - INSP OF THE THICK OF THE SKIN PANELLING OF THE VERT. SKIN | | 29-May-03 | 0 |
| ASB-BO 105 LS 10-11 | | BO 105 LS A-3 | LIFTING SYSTEM - LIFE LIMITED PARTS | | 19-May-05 | 0 |
| ASB-BO 105 LS 30-12 | | BO 105 LS A-3 | TAIL ROTOR CHECK OF BALANCE WEIGHTS AND CONTROL LEVER | | 12-Dec-08 | 0 |
| ASB-BO 105 LS 30-9 | | BO 105 LS A-3 | CRACKS FOUND IN TAILBOOM BLIND RIVETS | | 19-Nov-04 | 0 |
| ASB-BO 105 LS 80-28 | | BO 105 LS A-3 | SPONTANEOUS REELING-OUT OF THE WINCH CABLE | | 22-Jun-04 | 0 |

Service Bulletins, Service Information

Last Updated: 4 January 2022



| Report Number | STC / SN Number | Model | Report Title | Part Number | Date | Rev. |
|---------------------------|--|----------------|---|-------------|-----------|------|
| ASB-BO 105 LS 80-29 | | BO 105 LS A-3 | FIRE PROTECTION SYSTEM | | 11-Jun-07 | 0 |
| ASB-BO 105 LS 80-31 | | BO 105 LS A-3 | RESCUE HOIST | | 12-Jan-09 | 0 |
| ASB-BO 105 LS-30-11 | | BO 105 LS A-3 | TAIL ROTOR GEARBOX | | 28-May-08 | 0 |
| ASB-BO 105 LS-80-30 | | BO 105 LS A-3 | CARGO HOOK - CHECK KEEPER RETURN SPRING | | 24-Mar-08 | 0 |
| ASB-BO105 LS-10-9 | | BO105 LS | ALERT SERVICE BULLETIN | | 17-Sep-97 | 0 |
| ASB-BO105 LS-30-7 | | BO 105 LS A-3 | TAIL ROTOR DRIVE | | 18-Jul-03 | 1 |
| ASB- BO105LS-10- 10 | | BO 105 LS A-3 | MAIN ROTOR SYSTEM | | 28-May-08 | 1 |
| ASB-AHCA- 101 | SH97-33, O-LSH97-063/D, O-LSH97-075/D O-LS97-107/D O-LSH97-135/D O-LSH97-150/D O-LSH97-152/D | AS 350, AS 355 | REAR CARGO DOOR HINGE AND LATCH MODIFICATION | 350-201064 | 07-Oct-20 | 0 |
| | SH97-34 | AS 350, AS 355 | FORWARD-OPENING REAR CARGO DOOR | 350-201014 | | |
| | SH97-34 | EC 130 | FORWARD-OPENING REAR CARGO DOOR | 130-201004 | | |