



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|------------------|-------------------------------------|-----------------------------|-----------|------------------------------------|
| MMS-ECL-003 | | AS350 BA, B2, B3 | AIRFRAME FUEL FILTER | 350-600004 | | Superseded with ICA-ECL-130 |
| MMS-ECL-006 | SH96-31 | AS355 | BATTERY POWER SYSTEM RELOCATION | 350-700214/324 | | Superseded with ICA-ECL-125 |
| MMS-ECL-023 | | AS350/355 | SETTLING PROTECTORS | 350-500214 | | Superseded with ICA-ECL-124 |
| MMS-ECL-024 | | AS350/355 | AIRBORNE SATELLITE TELEPHONE SYSTEM | 350-901704 | 24-May-00 | 1 |
| MMS-ECL-028 | SH96-129 | AS350/355 | STIRRUP STEPS INSTALLATION | 350-201604 | 19-Apr-00 | 0 |
| MMS-ECL-029 | SH98-44 | AS350/355 | RAIL STEPS | 350-500194/204 | 11-Jul-00 | 0 |
| MMS-ECL-032 | | AS350 | PA / SIREN SYSTEM | 350-888594 | 27-Jul-00 | 0 |
| MMS-ECL-033 | SH97-36 | AS350 | COWLING MAINTENANCE STEPS | 350-200094/104 | 26-May-00 | 0 |
| MMS-ECL-035 | SH00-1 | AS350 | HIGH VISIBILITY DOOR | 350-202014 | 30-Aug-04 | 2 |
| MMS-ECL-036 | | AS350 | LEFT SIDE PILOT CONFIGURATION | 350-400004/74 350-400164 | | Superseded with ICA-ECL-168 |
| MMS-ECL-037 | | AS350/355 | SETTLING PROTECTORS | 120-500214 | | Superseded with ICA-ECL-026 |
| MMS-ECL-040 | SH96-115 | AS350 | FIREWALL REINFORCEMENT | 350-601014 | 30-Aug-04 | 1 |
| MMS-ECL-101 | O-LSH04-078 | AS350 B3 | MISSION EQUIPMENT MODIFICATIONS | 350-902804/904 | 24-May-12 | 5 |
| MMS-ECL-102 | O-LSH08-186D | AS350 B3 | FLIR U8000/U8500 SYSTEM | 350-903544 | 28-Aug-08 | 0 |
| MMS-ECL-103 | O-LSH07-049D | AS350 B3 | AUTOPILOT INTERFACE | 350-401144 | 28-Aug-08 | 0 |
| MMS-ECL-104 | O-LSH08-188D | AS350 B3 | COMM NAV | 350-880914 | 28-Aug-08 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|-----------------------|--------------------|-------------|-------------|
| MMS-ECL-105 | O-LSH08-187D | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902934 | 28-Aug-08 | 0 |
| MMS-ECL-106 | O-LSH09-200D | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902974 | 22-Jun-09 | 0 |
| MMS-ECL-107 | | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902984 | 03-Jul-09 | 0 |
| MMS-ECL-108 | O-LSH07-051D | AS350 B3 | FLIR U8500 | 350-903584 | 22-Jun-09 | 0 |