

AS 350 B3
SITUATION DES REVISIONS DU MANUEL DE VOL
FLIGHT MANUAL REVISIONS STATUS
CERTIFICATION EASA
EASA CERTIFICATION

Ce manuel doit contenir la révision normale (RN) et les révisions rapides (RR) référencées dans l'édition (EDIT) considérée.

This manual must contain the normal revision (RN) and rush revisions (RR) listed under the relevant issue (EDIT).

PARTIE REGLEMENTAIRE PRESCRIBED SECTION Volume 1		
SECT. / SUP.	. . EDIT .	. . DATE .
0 => 5.1	RN6	10-11
SUP.0	RN16	09-28
SUP.2		
SUP.4	RN2	06-18
SUP.6	RN3	06-18
SUP.7	RN1	03-25
SUP.11		
SUP.12	RN2	09-28
SUP.13	RN6	09-28
SUP.13.1	RN5	09-28
SUP.13.2	RN3	09-28
SUP.14	RN4	08-40
SUP.15	RN1	03-25
SUP.16	RN3	10-11
SUP.17	RN3	10-11
SUP.18	RN2	10-11
SUP.19	RN1	03-25
SUP.19.1	RN2	06-18
SUP.20	RN2	06-18
SUP.21	RN1	03-25
SUP.22	RN2	03-25

PARTIE REGLEMENTAIRE PRESCRIBED SECTION Volume 1		
SECT. / SUP.	. . EDIT .	. . DATE .
SUP.23	RN3	10-11
SUP.24	RN1	03-25
SUP.29	RN0	06-18
SUP.50	RN2	06-18
SUP.51	RN1	03-25
SUP.55	RN1	03-25
SUP.55.1	RN1	03-25
SUP.55.2	RN1	03-25
SUP.55.3	RN2	09-02
SUP.56	RN1	03-25

PARTIE COMPLEMENTAIRE COMPLEMENTARY SECTION Volume 2		
SECT.	EDIT	DATE
0, 6 => 10	RN7	09-28



Direction Technique
Support à la Clientèle
13725 Marignane Cedex – France
Tel : +33 (0)4 42 85 85 85 – Fax : +33 (0)4 42 85 85 00
Telex : HELIC 410 975 F
Télégramme : EUROCOPTER Marignane

Marignane, 29 March 2012

Subject: AS350B3, EASA Flight Manual Erratum

Dear customer,

An error has occurred in the issuing of the "SRD" page dated 01/03/2012 of your flight Manual:

The previous revisions of supplements SUP.13.1 and 13.2 are listed on the page by error and should not appear.

As a consequence, the "SRD" page dated 01/03/2012 must be replaced by the enclosed page:

- "SRD" page dated 01/03/2012.

The issue date of the replacement page remains the same but is underlined.

Yours sincerely,

Alain DELEBARRE
Light helicopters Flight Manuals

A handwritten signature in black ink, consisting of a stylized 'A' followed by a horizontal line and a vertical stroke.