

| Report Number | STC Number  | Model        | Report Title                          | Part Number | Date      | Rev. |
|---------------|-------------|--------------|---------------------------------------|-------------|-----------|------|
| FMS-ECL-003   | SH94-31     | AS350 B,BA   | AIRFRAME-MOUNTED FUEL FILTER          | 350-600004  | 15-May-07 | 4    |
| FMS-ECL-004   | SH94-31     | AS350 B1, B2 | AIRFRAME-MOUNTED FUEL FILTER          | 350-600004  | 15-May-07 | 4    |
| FMS-ECL-007   | SH 6-32     | AS350 BA, B2 | LEFT SIDE PILOT CONFIRGURATION        | 350-400004  | 25-May-10 | 5    |
| FMS-ECL-008   | SH96-39     | AS350        | TWO PLACE FORWARD PASSENGER SEAT (RH) | 350-200624  | 02-May-02 | 5    |
| FMS-ECL-009   | SH97-15     | AS350/355    | LH AND/OR RH CARGO PODS INSTALLATION  | 350-200814  | 07-May-98 | 2    |
| FMS-ECL-010   | SH96-113    | AS350/355    | AFT CABIN DOORS REMOVED               |             | 09-Aug-00 | 1    |
| FMS-ECL-015   | SH02-42     | AS350 B3     | AIRFRAME-MOUNTED FUEL FILTER          | 350-600024  | 10-Apr-08 | 6    |
| FMS-ECL-016A  | O-LSH98-344 | EC120 B      | NAVIGATION DISPLAY                    |             | 21-Dec-99 | 0    |
| FMS-ECL-019   | SH96-32     | AS350 B3     | LEFT SIDE PILOT CONFIGURATION         | 350-400074  | 25-May-10 | 5    |
| FMS-ECL-022A  | O-LSH99-078 | EC120 B      | NAVIGATIONAL DISPLAY                  |             | 16-Apr-99 | 0    |
| FMS-ECL-027B  | O-LSH01-065 | AS350 B      | NAVIGATION DISPLAY                    |             | 15-Aug-01 | 0    |
| FMS-ECL-028A  | O-LSH00-017 | AS350 B3     | AUTOPILOT HEADING SUB MODE            |             | 04-Oct-00 | 0    |

| Report Number | STC Number    | Model    | Report Title   | Part Number | Date      | Rev. |
|---------------|---------------|----------|--|-------------|-----------|------|
| FMS-ECL-028B  | O-LSH01-056   | AS350 B  | AUTOPILOT HEADING SUB MODE   |             | 15-Aug-01 | 0    |
| FMS-ECL-031C  | O-LSH01-028   | EC120 B  | NAVIGATION DISPLAY (S/M 1136)  |             | 15-Aug-01 | 0    |
| FMS-ECL-032A  | O-LSH01-087   | EC120 B  | FLIR 445G MARK 2 SYSTEM  |             | 11-Dec-01 | 2    |
| FMS-ECL-035A  | O-LSH00-096   | AS350 B2 | FLOOR MOUNTED TORQUE METER   |             | 17-May-00 | 0    |
| FMS-ECL-037   | SH96-32       | AS350 B3 | LEFT SIDE PILOT CONFIGURATION  | 350-400164  | 25-May-10 | 4    |
| FMS-ECL-038A  |               | EC120 B  | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-038B  |               | EC120 B  | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM                     |             | 27-Jun-01 | 0    |
| FMS-ECL-038C  |               | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-038D  |               | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-100A  | O-LSH02-6721D | EC120 B  | FLIR SYSTEM  |             | 20-Nov-02 | 0    |
| FMS-ECL-101   |               | EC120 B  | SX-16 SEARCHLIGHT INSTALLATION   |             | 20-Nov-02 | 0    |
| FMS-ECL-102   | SH02-39       | EC120 B  | IMPROVED HEATING SYSTEM  | 120-701014  | 19-Oct-10 | 4    |
| FMS-ECL-103   | SH02-42       | EC130 B4 | AIRFRAME-MOUNTED FUEL FILTER   | 130-600004  | 10-Apr-08 | 5    |
| FMS-ECL-105   | SH02-45       | EC130 B4 | LITTER KIT   | 130-200034  | 28-Nov-07 | 1    |

| Report Number | STC Number  | Model            | Report Title  | Part Number    | Date      | Rev. |
|---------------|-------------|------------------|---|----------------|-----------|------|
| FMS-ECL-106   | O-LSH03-70  | AS350 B3         | OPERATION WITH LEFT HAND PILOT DOOR<br>REMOVED                                |                | 01-Apr-03 | 0    |
| FMS-ECL-107   | SH94-29     | AS350/355        | LEFT HAND LITTER KIT  | 350-200034     | 11-Dec-06 | 5    |
| FMS-ECL-108   | SH96-62     | AS350 BA, B2, B3 | RIGHT HAND LITTER KIT   | 350-200144     | 15-Dec-08 | 4    |
| FMS-ECL-109   | SH03-15     | EC120 B          | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER<br>MOUNT (W/OUT PILOT'S CYCLIC CONTROL) | 120-901234     | 09-Nov-05 | 1    |
| FMS-ECL-110   | SH03-15     | EC120 B          | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER<br>MOUNT (WITH PILOT'S CYCLIC CONTROL)  | 120-901234     | 09-Nov-05 | 1    |
| FMS-ECL-111   | O-LSH03-207 | AS350 B3         | AUTOPILOT HEADING SUB-MODE  | 350-401124     | 25-Mar-04 | 1    |
| FMS-ECL-112   | SH04-53     | EC130 B4         | OPERATION WITH SANDFILTER REMOVED   | 130-800034     | 30-Nov-04 | 0    |
| FMS-ECL-114   | SH03-15     | EC120 B          | SX-16 SEARCHLIGHT INSTALLATION WITH SLASS                                     | 120-901234     | 09-Nov-05 | 0    |
| FMS-ECL-115   | SH05-47     | EC 120 B         | FLIR U8500/U8500 SYSTEM INSTALLATION  | 120-901814     | 04-Dec-08 | 1    |
| FMS-ECL-116   | O-LSH05-310 | EC120 B          | VIDEO DOWNLINK SYSTEM   | 120-902904     | 19-May-06 | 1    |
| FMS-ECL-117   | SH06-12     | AS350/355        | ENLARGED VERTICAL REFERENCE WINDOW  | 350/355-201154 | 13-Jul-06 | 1    |
| FMS-ECL-118   | O-LSH06-309 | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8  | 120-880204     | 18-Apr-07 | 3    |
| FMS-ECL-119   | O-LSH06-329 | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8  | 120-880204     | 16-Apr-07 | 2    |
| FMS-ECL-120   | O-LSH06-337 | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM &<br>AUTOPILOT                                | 120-880214     | 05-Apr-07 | 3    |

| Report Number | STC Number    | Model    | Report Title                           | Part Number | Date      | Rev. |
|---------------|---------------|----------|--|-------------|-----------|------|
| FMS-ECL-121   | O-LSH07-050D  | AS350 B3 | VIDEO DOWNLINK SYSTEM                  | 350-902924  | 20-Feb-06 | 0    |
| FMS-ECL-122   | O-LSH07-0491D | AS350 B3 | AUTOPILOT HEADING SUBMODE              | 350-401144  | 28-Aug-08 | 1    |
| FMS-ECL-126   | O-LSH08-187D  | AS350    | VIDEO DOWNLINK SYSTEM                  | 350-902934  | 28-Aug-08 | 0    |
| FMS-ECL-127   | O-LSH08-282D  | EC120 B  | VIDEO DOWNLINK SYSTEM (STRATA DIGITAL) | 120-902934  | 12-Dec-08 | 0    |
| FMS-ECL-128   | O-LSH08-288   | AS350 B3 | COMM NAV SYSTEM                        |             | 20-Jul-10 | 5    |
| FMS-ECL-129   | O-LSH08-288   | AS350 B3 | TWO PLACE FORWARD PASSENGER SEAT       | 350-200624  | 19-Dec-08 | 0    |
| FMS-ECL-130   | O-LSH08-288   | AS350 B3 | LH PILOT CONFIGURATION                 | 350-400164  | 19-Dec-08 | 0    |
| FMS-ECL-133   | SH09-11       | AS350 B2 | DUAL SAGEM ICDS-6A INSTALLATION        | 350-873044  | 21-Apr-09 | 0    |
| FMS-ECL-134   | O-LSH09-245   | EC120 B  | DUAL SAGEM ICDS-6A                     | 120-872744  | 11-Aug-09 | 3    |
| FMS-ECL-135   | O-LSH09-200D  | AS350 B3 | VIDEO DOWNLINK SYSTEM                  | 350-902974  | 22-Jun-09 | 0    |
| FMS-ECL-136   | O-LSH09-210D  | AS350 B3 | VIDEO DOWNLINK SYSTEM                  | 350-902984  | 03-Jul-09 | 0    |
| FMS-ECL-137   | SH10-20       | EC130 B4 | OPERATION WITH DOORS REMOVED           |             | 26-Apr-10 | 0    |
| FMS-ECL-138   | O-LSH10-308   | EC120 B  | FLIR U8500 SYSTEM INSTALLATION         | 120-901864  | 30-Nov-10 | 1    |
| FMS-ECL-139   | O-LSH11-066   | EC135    | FLIR INSTALLATION                      | 135-901814  | 21-Apr-11 | 0    |

| Report Number | STC Number     | Model    | Report Title                      | Part Number | Date      | Rev. |
|---------------|----------------|----------|-----------------------------------|-------------|-----------|------|
| FMS-ECL-140   | O-LSH11-065    | EC135    | SX-16 INSTALLATION                | 135-901214  | 21-Apr-11 | 0    |
| FMS-ECL-141   | O-LSH11-070    | EC135    | VIDEO DOWNLINK                    | 135-902714  | 15-Apr-11 | 0    |
| FMS-ECL-142   | O-LSH11-069    | EC135    | DOOR OPEN WARNING                 | 135-901014  | 15-Apr-11 | 0    |
| FMS-ECL-143   | O-LSH11-073/D  | AS350 B2 | COMM NAV SYSTEM                   | 350-880974  | 20-Apr-11 | 1    |
| FMS-ECL-144   | O-LSH11-068    | EC135    | CARGO COMPARTMENT MODS            | 135-200304  | 13-Apr-11 | 0    |
| FMS-ECL-145   | O-LSH11-0081/D | AS350 B3 | BMS DOWNLINK                      | 350-902994  | 10-May-11 | 1    |
| FMS-ECL-146   | O-LSH11-074/D  | EC135    | PULSE LIGHT INSTALLATION          | 135-902414  | 18-Apr-11 | 0    |
| FMS-ECL-148   | SH11-35        | EC130 B4 | ADJUSTABLE GLARE SHIELD           | 130-885114  | 20-Sep-11 | 0    |
| FMS-ECL-149   | O-LSH11-111    | AS350 B3 | ADJUSTABLE GLARE SHIELD           | ESK-1457    | 17-Jun-11 | 0    |
| FMS-ECL-151   | SH12-16        | AS350 B3 | OPERATION WITH SANDFILTER REMOVED | 350-800044  | 13-Mar-12 | 2    |