



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|-------------------|--------------|---------------------------------------|----------------------------------|-------------|------|
| FMS-ECL-003 | SH94-31 | AS350 B,BA | AIRFRAME-MOUNTED FUEL FILTER | 350-600004 | 28-May-15 | 5 |
| FMS-ECL-004 | SH94-31 | AS350 B1, B2 | AIRFRAME-MOUNTED FUEL FILTER | 350-600004 | 28-May-15 | 5 |
| FMS-ECL-007 | SH96-32 | AS350 BA, B2 | LEFT SIDE PILOT CONFIRGURATION | 350-400004 | 25-Oct-2013 | 8 |
| FMS-ECL-008 | SH96-39 | AS350 | TWO PLACE FORWARD PASSENGER SEAT (RH) | 350-200624 | 05-Nov-12 | 6 |
| FMS-ECL-009 | SH97-15 / SH97-60 | AS350/355 | LH AND/OR RH CARGO PODS INSTALLATION | 350-200814/824 355-200814/824 | 02-Mar-15 | 4 |
| FMS-ECL-010 | SH96-113 | AS350/355 | AFT CABIN DOORS REMOVED | | 09-Aug-00 | 1 |
| FMS-ECL-015 | SH02-42 | AS350 B3 | AIRFRAME-MOUNTED FUEL FILTER | 350-600024 | 19-Dec-12 | 7 |
| FMS-ECL-016A | O-LSH98-344 | EC120 B | NAVIGATION DISPLAY | | 21-Dec-99 | 0 |
| FMS-ECL-019 | SH96-32 | AS350 B3 | LEFT SIDE PILOT CONFIGURATION | 350-400074 | 25-May-10 | 5 |
| FMS-ECL-022A | O-LSH99-078 | EC120 B | NAVIGATIONAL DISPLAY | | 16-Apr-99 | 0 |
| FMS-ECL-027B | O-LSH01-065 | AS350 B | NAVIGATION DISPLAY | | 15-Aug-01 | 0 |
| FMS-ECL-028A | O-LSH00-017 | AS350 B3 | AUTOPILOT HEADING SUB MODE | | 04-Oct-00 | 0 |
| FMS-ECL-028B | O-LSH01-056 | AS350 B | AUTOPILOT HEADING SUB MODE | | 15-Aug-01 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|----------|--|-------------|-----------|------|
| FMS-ECL-031C | O-LSH01-028 | EC120 B | NAVIGATION DISPLAY (S/M 1136) | | 15-Aug-01 | 0 |
| FMS-ECL-032A | O-LSH01-087 | EC120 B | FLIR 445G MARK 2 SYSTEM | | 11-Dec-01 | 2 |
| FMS-ECL-035A | O-LSH00-096 | AS350 B2 | FLOOR MOUNTED TORQUE METER | | 17-May-00 | 0 |
| FMS-ECL-037 | SH96-32 | AS350 B3 | LEFT SIDE PILOT CONFIGURATION | 350-400164 | 05-Nov-12 | 5 |
| FMS-ECL-038A | | EC120 B | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 | | 10-Jul-03 | 0 |
| FMS-ECL-038B | | EC120 B | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM | | 27-Jun-01 | 0 |
| FMS-ECL-038C | | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 | | 10-Jul-03 | 0 |
| FMS-ECL-038D | | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 | | 10-Jul-03 | 0 |
| FMS-ECL-100A | O-LSH02-6721D | EC120 B | FLIR SYSTEM | | 20-Nov-02 | 0 |
| FMS-ECL-101 | | EC120 B | SX-16 SEARCHLIGHT INSTALLATION | | 20-Nov-02 | 0 |
| FMS-ECL-102 | SH02-39 | EC120 B | IMPROVED HEATING SYSTEM | 120-701014 | 19-Oct-10 | 4 |
| FMS-ECL-103 | SH02-42 | EC130 B4 | AIRFRAME-MOUNTED FUEL FILTER | 130-600004 | 10-Apr-08 | 5 |
| FMS-ECL-105 | SH02-45 | EC130 B4 | LITTER KIT | 130-200034 | 28-Nov-07 | 1 |
| FMS-ECL-106 | O-LSH03-70 | AS350 B3 | OPERATION WITH LEFT HAND PILOT DOOR REMOVED | | 01-Apr-03 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|------------------|--|----------------|-----------|------|
| FMS-ECL-107 | SH94-29 | AS350/355 | LEFT HAND LITTER KIT | 350-200034 | 11-Dec-06 | 5 |
| FMS-ECL-108 | SH96-62 | AS350 BA, B2, B3 | RIGHT HAND LITTER KIT | 350-200144 | 15-Dec-08 | 4 |
| FMS-ECL-109 | SH03-15 | EC120 B | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER MOUNT (W/OUT PILOT'S CYCLIC CONTROL) | 120-901234 | 09-Nov-05 | 1 |
| FMS-ECL-110 | SH03-15 | EC120 B | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER MOUNT (WITH PILOT'S CYCLIC CONTROL) | 120-901234 | 09-Nov-05 | 1 |
| FMS-ECL-111 | O-LSH03-207 | AS350 B3 | AUTOPILOT HEADING SUB-MODE | 350-401124 | 25-Mar-04 | 1 |
| FMS-ECL-112 | SH04-53 | EC130 B4 | OPERATION WITH SANDFILTER REMOVED | 130-800034 | 30-Nov-04 | 0 |
| FMS-ECL-114 | SH03-15 | EC120 B | SX-16 SEARCHLIGHT INSTALLATION WITH SLASS | 120-901234 | 09-Nov-05 | 0 |
| FMS-ECL-115 | SH05-47 | EC 120 B | FLIR U8500/U8500 SYSTEM INSTALLATION | 120-901814 | 04-Dec-08 | 1 |
| FMS-ECL-116 | O-LSH05-310 | EC120 B | VIDEO DOWNLINK SYSTEM | 120-902904 | 19-May-06 | 1 |
| FMS-ECL-117 | SH06-12 | AS350/355 | ENLARGED VERTICAL REFERENCE WINDOW | 350/355-201154 | 28-Jan-15 | 4 |
| FMS-ECL-118 | O-LSH06-309 | EC120 B | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8 | 120-880204 | 18-Apr-07 | 3 |
| FMS-ECL-119 | O-LSH06-329 | EC120 B | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8 | 120-880204 | 16-Apr-07 | 2 |
| FMS-ECL-120 | O-LSH06-337 | EC120 B | COMM NAV SYSTEM WITH DUAL SAGEM & AUTOPILOT | 120-880214 | 05-Apr-07 | 3 |
| FMS-ECL-121 | O-LSH07-050D | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902924 | 20-Feb-06 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|---------------|----------|---|-------------|-----------|------|
| FMS-ECL-122 | O-LSH07-0491D | AS350 B3 | AUTOPILOT HEADING SUBMODE | 350-401144 | 28-Aug-08 | 1 |
| FMS-ECL-126 | O-LSH08-187D | AS350 | VIDEO DOWNLINK SYSTEM | 350-902934 | 28-Aug-08 | 0 |
| FMS-ECL-127 | O-LSH08-282D | EC120 B | VIDEO DOWNLINK SYSTEM (STRATA DIGITAL) | 120-902934 | 12-Dec-08 | 0 |
| FMS-ECL-128 | O-LSH08-288 | AS350 B3 | COMM NAV SYSTEM | | 20-Jul-10 | 5 |
| FMS-ECL-129 | O-LSH08-288 | AS350 B3 | TWO PLACE FORWARD PASSENGER SEAT | 350-200624 | 19-Dec-08 | 0 |
| FMS-ECL-130 | O-LSH08-288 | AS350 B3 | LH PILOT CONFIGURATION | 350-400164 | 19-Dec-08 | 0 |
| FMS-ECL-131 | | EC120 B | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880204 | 09-Jan-13 | 0 |
| FMS-ECL-132 | | EC120 B | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880214 | 09-Jan-13 | 0 |
| FMS-ECL-133 | SH09-11 | AS350 B2 | DUAL SAGEM ICDS-6A INSTALLATION | 350-873044 | 21-Apr-09 | 0 |
| FMS-ECL-134 | O-LSH09-245 | EC120 B | DUAL SAGEM ICDS-6A | 120-872744 | 11-Aug-09 | 3 |
| FMS-ECL-135 | O-LSH09-200D | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902974 | 22-Jun-09 | 0 |
| FMS-ECL-136 | O-LSH09-210D | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902984 | 03-Jul-09 | 0 |
| FMS-ECL-137 | SH10-20 | EC130 B4 | OPERATION WITH DOORS REMOVED | | 18-Dec-13 | 2 |
| FMS-ECL-138 | O-LSH10-308 | EC120 B | FLIR U8500 SYSTEM INSTALLATION | 120-901864 | 30-Nov-10 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|-----------------------------------|--------------------|-------------|-------------|
| FMS-ECL-139 | O-LSH11-066 | EC135 | FLIR INSTALLATION | 135-901814 | 21-Apr-11 | 0 |
| FMS-ECL-140 | O-LSH11-065 | EC135 | SX-16 INSTALLATION | 135-901214 | 21-Apr-11 | 0 |
| FMS-ECL-141 | O-LSH11-070 | EC135 | VIDEO DOWNLINK | 135-902714 | 15-Apr-11 | 0 |
| FMS-ECL-142 | O-LSH11-069 | EC135 | DOOR OPEN WARNING | 135-901014 | 15-Apr-11 | 0 |
| FMS-ECL-143 | O-LSH11-073/D | AS350 B2 | COMM NAV SYSTEM | 350-880974 | 20-Apr-11 | 1 |
| FMS-ECL-144 | O-LSH11-068 | EC135 | CARGO COMPARTMENT MODS | 135-200304 | 13-Apr-11 | 0 |
| FMS-ECL-145 | O-LSH11-0081/D | AS350 B3 | BMS DOWNLINK | 350-902994 | 10-May-11 | 1 |
| FMS-ECL-146 | O-LSH11-074/D | EC135 | PULSE LIGHT INSTALLATION | 135-902414 | 18-Apr-11 | 0 |
| FMS-ECL-148 | SH11-35 | EC130 B4 | ADJUSTABLE GLARE SHIELD | 130-885114 | 20-Sep-11 | 0 |
| FMS-ECL-149 | O-LSH11-111 | AS350 B3 | ADJUSTABLE GLARE SHIELD | ESK-1457 | 17-Jun-11 | 0 |
| FMS-ECL-151 | SH12-16 | AS350 B3 | OPERATION WITH SANDFILTER REMOVED | 350-800044 | 13-Mar-12 | 2 |
| FMS-ECL-153 | O-LSH12-189 | AS350 B3 | COMM NAV SYSTEM | 350-881014 | 10-Dec-12 | 0 |
| FMS-AHCA-152 | SH14-10 | AS350 B2, B3 | LONG LINE ELECTRICAL PROVISIONS | 350-900564 | 29-Apr-15 | 3 |
| FMS-ECL-154 | SH02-42 | AS350 B3 | AIRFRAME-MOUNTED FUEL FILTER | 350-600024 | 21-Dec-12 | 2 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|---|--------------------|-------------|-------------|
| FMS-ECL-155 | SH96-31 | AS350/355 | BATTERY RELOCATION | 350-700324 | 03-Jul-13 | 1 |
| FMS-AHCA-159 | O-LSH14-148/D | AS355 NP | LEAD ACID BATTERY INSTALLATION | 355-700024 | 12-Dec-14 | 0 |
| FMS-AHCA-160 | O-LSH14-150/D | AS355 NP | 50 AMP / LONGLINE / CAROUSEL | 355-900034 | 12-Dec-14 | 0 |
| FMS-AHCA-161 | O-LSH14-147/D | AS355 NP | FLIGHT FOLLOWING SATPHONE | 355-903014 | 12-Dec-14 | 0 |
| FMS-AHCA-162 | O-LSH14-149/D | AS355 NP | PULSE LIGHT INSTALLATION | 355-902414 | 12-Dec-14 | 0 |
| FMS-AHCA-164 | O-LSH14-138/D | AS355 NP | COMM NAV SYSTEM | 355-880054 | 12-Dec-14 | 0 |
| FMS-AHCA-165 | SH15-7 | AS 355 N, NP | INSTALLATION OF HIGH VISIBILITY FORWARD CABIN DOORS | 350-202014 | 04-May-15 | 1 |
| FMS-AHCA-166 | SH12-52 | AS355 | CABLE CUTTER INSTALLATION | 350-252004 | 19-Feb-15 | 0 |