



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|------------|----------|---|------------------------|-----------|------|
| ICA-ECL-025 | | AS350 B3 | COMM NAV SYSTEM | 350-870854 | 17-Feb-04 | 0 |
| ICA-ECL-026 | SH00-30 | EC120B | SETTLING PROTECTORS | 120-500214-02 | 19-May-05 | 3 |
| ICA-ECL-029 | | EC120B | COMM NAV SYSTEM STANDARD PACKAGE | | 13-Sep-00 | 1 |
| ICA-ECL-030 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870484 | 13-Sep-00 | 1 |
| ICA-ECL-031 | | EC120B | COMM NAV INSTALLATION, STANDARD PACKAGE | 120-870494 | 13-Sep-00 | 1 |
| ICA-ECL-032 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870444 | 13-Sep-00 | 1 |
| ICA-ECL-033 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870544 | 13-Sep-00 | 1 |
| ICA-ECL-034 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870454, 120-870504 | 13-Sep-00 | 1 |
| ICA-ECL-035 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870654 | 13-Sep-00 | 1 |
| ICA-ECL-036 | | EC120B | COMM NAV INSTALLATION, STANDARD PACKAGE | 120-870404 | 13-Sep-00 | 1 |
| ICA-ECL-037 | | EC120B | DIRECTIONAL GYRO | 120-870274 | 29-Apr-02 | 2 |
| ICA-ECL-038 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870074 | 13-Sep-00 | 1 |
| ICA-ECL-039 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870114 | 13-Sep-00 | 1 |
| ICA-ECL-040 | | EC120B | COM NAV INSTALLATION, STANDARD PACKAGE | 120-870094 | 13-Sep-00 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|------------|--------|--|-------------|-----------|------|
| ICA-ECL-041 | | EC120B | SLASS SYSTEM | | 25-Jun-01 | 0 |
| ICA-ECL-042A | | EC120B | FLIR SYSTEM | 120-901014 | 21-Dec-01 | 4 |
| ICA-ECL-100 | | EC120B | PA/SPEAKER | 120-888414 | 10-Jul-03 | 2 |
| ICA-ECL-101 | | EC120B | GPS NAVIGATIONSYSTEM | 120-870894 | 29-Apr-02 | 0 |
| ICA-ECL-102 | | EC120B | BASIC KY-196 VHF COMM 1 VHF TRANSCEIVER SYSTEM | 120-870484 | 29-Apr-02 | 0 |
| ICA-ECL-103 | | EC120B | BASIC AND ENHANCED 4000-10A ELT SYSTEM | 120-870914 | 29-Apr-02 | 0 |
| ICA-ECL-104 | | EC120B | BASIC AND ENHANCED DIGITAL CLOCK | 120-870934 | 29-Apr-02 | 0 |
| ICA-ECL-105 | | EC120B | ENHANCED KT-76C TRANSPONDER SYSTEM | 120-870944 | 29-Apr-02 | 0 |
| ICA-ECL-106 | | EC120B | BASIC KT-76A TRANSPONDER SYSTEM | 120-870454 | 29-Apr-02 | 0 |
| ICA-ECL-107 | | EC120B | BASIC AND ENHANCED 200HM ELT SYSTEM | 120-870924 | 29-Apr-02 | 0 |
| ICA-ECL-108 | | EC120B | COMM/NAV SYSTEM STANDARD PACKAGE TC TYPE CERTIFICATE | | 04-Dec-01 | 0 |
| ICA-ECL-109 | | EC120B | STANDARD PACKAGE, BASIC AND ENHANCED AMS-42 AUDIO SYSTEM | 120-870904 | 02-May-00 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|-----------|--|--|-----------|------|
| ICA-ECL-110 | | EC120B | STANDARD PACKAGE, ENHANCED COMM 1 SYSTEM | 120-870534 | 02-May-02 | 0 |
| ICA-ECL-111 | | EC130 B4 | AFT RH CABIN DOOR RETROFIT | 130-202424 | 10-Jul-03 | 1 |
| ICA-ECL-112 | SH02-38 | EC130 B4 | COWLING MAINTENANCE STEPS | 130-200094/104 | 22-Nov-02 | 0 |
| ICA-ECL-114 | O-LSH02-057 | EC 120B | COMM NAV EQUIPMENT | 120-889654, 120-883174, 120-884774 | 11-Oct-02 | 0 |
| ICA-ECL-116A | O-LSH02-672D | EC120B | FLIR SYSTEM | 120-901064 | 20-Nov-02 | 2 |
| ICA-ECL-117 | SH02-39 | EC120B | IMPROVED HEATING SYSTEM | 120-701014 | 10-May-13 | 7 |
| ICA-ECL-118 | SH02-42 | EC130 B4 | AIRFRAME FUEL FILTER | 130-600004 | 08-Apr-13 | 8 |
| ICA-ECL-119 | SH02-45 | EC130 B4 | LITTER KIT FOR 7 & 8 PLACE | 130-200034 | 09-Jun-05 | 3 |
| ICA-ECL-120 | SH02-44 | EC130 B4 | CARGO PODS | 130-200814 | 30-Dec-02 | 0 |
| ICA-ECL-122 | SH03-15 | EC120B | SPECTROLAB SX-16 NIGHTSUN SEARCHLIGHT | 120-901234 | 20-Mar-06 | 2 |
| ICA-ECL-123 | SH03-33 | EC130 B4 | CARGO POD INSTALLATION | 130-201024 | 11-Apr-13 | 4 |
| ICA-ECL-124 | SH01-22 | AS350/355 | SETTLING PROTECTORS | 120-500214-01 | 19-May-05 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|------------------------|--------------------------------------|--------------------|-------------|-------------|
| ICA-ECL-125 | SH96-31 | AS350/355 | BATTERY RELOCATION | 350-700324 | 24-Oct-13 | 12 |
| ICA-ECL-126 | SH96-32 | AS350 | RIGHT HAND LITTER KIT | 350-200144 | 15-Dec-08 | 3 |
| ICA-ECL-127 | SH94-29 | AS350/355 | LEFT HAND LITTER KIT | 350-200034 | 01-Nov-06 | 4 |
| ICA-ECL-128 | SH04-28 | EC130 B4 | AFT BENCH SEAT | 130-700614 | 19-Feb-08 | 4 |
| ICA-ECL-129 | SH02-42 | AS350 B3 | AIRFRAME FUEL FILTER | 350-600024 | 08-Apr-13 | 6 |
| ICA-ECL-130 | SH94-31 | AS350 B, BA, B1, B2 | AIRFRAME FUEL FILTER | 350-600004 | 09-Apr-13 | 4 |
| ICA-ECL-131 | SH96-61 | AS350/355 | CARGO MIRROR INSTALLATION | 350-200254/64 | 10-Sep-04 | 0 |
| ICA-ECL-132 | SH96-114 | AS350 | BELLY-MOUNTED ANTI-COLLISION LIGHT | 350-900624 | 10-Mar-08 | 1 |
| ICA-ECL-133 | SH05-18 | AS350 | HIGH VISIBILITY DOOR (SHORT) | 350-202414 | 18-Apr-13 | 2 |
| ICA-ECL-134 | SH04-53 | EC130 B4 | OPERATION WITH SANDFILTER REMOVED | 130-800034 | 30-Nov-04 | 0 |
| ICA-ECL-136 | SH05-39 | EC130 B4 | WIRE STRIKE PROTECTION SYSTEM | 130-300214 | 08-Sep-05 | 0 |
| ICA-ECL-137 | SH05-47 | EC120B | FLIR U8000/U8500 SYSTEM INSTALLATION | 120-901814 | 04-Dec-08 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|-------------|-----------|---|------------------------|-----------|------|
| ICA-ECL-138 | O-LSH05-310 | EC120B | VIDEO DOWNLINK SYSTEM | 120-902904 | 19-May-06 | 1 |
| ICA-ECL-139 | SH06-11 | EC130 B4 | HEAVY DUTY BATTERY INSTALLATION | 130-700214 | 20-Mar-06 | 0 |
| ICA-ECL-140 | SH06-12 | AS350/355 | ENLARGED VERTICAL REFERENCE WINDOW | 350-201154 | 09-Jul-08 | 2 |
| ICA-ECL-141 | SH97-34 | AS350/355 | FORWARD OPENING REAR CARGO DOOR | 350-201014, 130-201004 | 30-May-13 | 5 |
| ICA-ECL-143 | SH06-28 | AS350 | POP IMAGING SYSTEM | 350-903214 | 15-Jun-07 | 2 |
| ICA-ECL-144 | | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902924 | 19-Feb-06 | 0 |
| ICA-ECL-145 | | AS350 B3 | FLIR U7000 SYSTEM INSTALLATION | 350-903504 | 21-Feb-06 | 0 |
| ICA-ECL-147 | SH07-50 | EC130 B4 | COMM NAV SYSTEM MODIFICATION | 130-883004 | 27-Aug-08 | 2 |
| ICA-ECL-148 | SH07-48 | AS350 B3 | COMM NAV SYSTEM MODIFICATION | 350-880934 | 16-Apr-10 | 3 |
| ICA-ECL-149 | SH05-16 | AS350 B3 | COMM NAV SYSTEM MODIFICATION | 350-880884 | 12-May-08 | 0 |
| ICA-ECL-150 | SH99-205 | AS350 | PUBLIC ADDRESS / SIREN SYSTEM | 350-888594 | 30-Nov-07 | 0 |
| ICA-ECL-151 | | EC120 B | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880214 | 09-Jan-13 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|--------------|----------|---|-----------------|------------|------|
| ICA-ECL-152 | O-LSH98-107 | AS350 B3 | SECURITY BARRIER | 350-702014 | 03-Feb-10 | 1 |
| ICA-ECL-153 | O-LSH07-020 | AS350 B3 | MISSION EQUIPMENT RACK | 350-902824 | 25-Apr-08 | 0 |
| ICA-ECL-154 | O-LSH07-015 | AS350 B3 | ALTERNATIVE LIGHTING SYSTEM | 350-902524 | 29-Aug-08 | 1 |
| ICA-ECL-155 | O-LSH08-283D | EC120B | ALTERNATE LIGHTING | 120-903214 | 11-Dec-08 | 0 |
| ICA-ECL-156 | O-LSH08-282 | EC120B | VIDEO DOWNLINK SYSTEM | 120-902934 | 12-Dec-08 | 1 |
| ICA-ECL-157 | O-LSH08-288 | AS350 B3 | COMM NAV SYSTEM | 350-880944 | 19-Dec-08 | 0 |
| ICA-ECL-158 | O-LSH08-288 | AS350 B3 | LH PILOT CONFIGURATION | 350-400164 | 15-Jul-09 | 1 |
| ICA-ECL-161 | | AS350 B3 | TWO PLACE FORWARD PASSENGER SEAT | 350-200624 | 19-Dec-08 | 0 |
| ICA-ECL-162 | O-LSH08-298 | AS350 B3 | DUAL BATTERY INSTALLATION | 350 A62 2537 00 | 17-June-13 | 3 |
| ICA-ECL-163 | | EC120 B | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880204 | 09-Jan-13 | 0 |
| ICA-ECL-164 | O-LSH09-081 | AS350 B2 | COMM NAV SYSTEM | 350-880954 | 21-Apr-09 | 1 |
| ICA-ECL-165 | SH09-11 | AS350 B2 | DUAL SAGEM ICDS-6 INSTALLATION | 350-873044 | 04-Nov-09 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|------------------------|------------------------------|-------------|-------------|
| ICA-ECL-166 | O-LSH09-127 | AS350 B2 | INTERIOR | 350-701614 | 27-Apr-09 | 0 |
| ICA-ECL-167 | O-LSH09-128 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701624 | 14-Sep-09 | 2 |
| ICA-ECL-168 | SH96-32 | AS350 | LEFT SIDE PILOT | 350-400004/74, 350-400164 | 25-Oct-13 | 6 |
| ICA-ECL-169 | O-LSH09-123 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701614 | 14-Nov-13 | 7 |
| ICA-ECL-170 | O-LSH09-245 | EC120B | DUAL SAGEM ICDS-6A | 120-872744 | 31-Jul-09 | 2 |
| ICA-ECL-171 | O-LSH09-247 | EC120B | COMM NAV SYSTEM | 120-880284 | 31-Jul-09 | 1 |
| ICA-ECL-172 | O-LSH09-142 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701624 | 11-May-09 | 0 |
| ICA-ECL-173 | O-LSH09-141 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701634 | 06-May-09 | 0 |
| ICA-ECL-174 | O-LSH09-145 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701634 | 08-Sep-09 | 1 |
| ICA-ECL-175 | O-LSH09-224D | EC120B | INTERIOR MODIFICATIONS | 120-701614 | 22-Jul-09 | 1 |
| ICA-ECL-177 | O-LSH09-202 | EC120B | INTERIOR MODIFICATIONS | 120-701624 | 25-Jun-09 | 0 |
| ICA-ECL-178 | O-LSH09-263D | AS350 B3 | INTERIOR MODIFICATIONS | 350-701644 | 18-Aug-09 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|------------------------|--------------------|-------------|-------------|
| ICA-ECL-179 | O-LSH09-266D | EC130 B4 | INTERIOR MODIFICATIONS | 130-701644 | 18-Sep-09 | 1 |
| ICA-ECL-180 | O-LSH09-264D | AS350 | INTERIOR MODIFICATIONS | 350-701684 | 27-Aug-09 | 0 |
| ICA-ECL-181 | O-LSH09-354 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701664 | 24-Nov-09 | 0 |
| ICA-ECL-182 | O-LSH09-0342 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701654 | 04-Nov-09 | 0 |
| ICA-ECL-183 | O-LSH09-0343 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701674 | 04-Nov-09 | 0 |
| ICA-ECL-184 | O-LSH09-379 | AS350 | INTERIOR MODIFICATIONS | 350-701694 | 07-Dec-09 | 0 |
| ICA-ECL-185 | O-LSH09-355 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701704 | 29-Jul-10 | 1 |
| ICA-ECL-186 | O-LSH10-103 | AS350 | INTERIOR MODIFICATIONS | 350-701714 | 27-Apr-10 | 1 |
| ICA-ECL-187 | O-LSH10-019 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701724 | 25-Jan-10 | 0 |
| ICA-ECL-188 | O-LSH10-104 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701744 | 26-Apr-10 | 0 |
| ICA-ECL-189 | O-LSH10-091 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701754 | 13-Apr-10 | 1 |
| ICA-ECL-190 | O-LSH10-102 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701734 | 14-Jan-11 | 3 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|----------------------------------|--------------------|-------------|-------------|
| ICA-ECL-191 | SH10-20 | EC130 B4 | OPERATION WITH DOORS REMOVED | | 18-Dec-13 | 3 |
| ICA-ECL-192 | O-LSH10-114 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701654 | 05-May-10 | 0 |
| ICA-ECL-194 | O-LSH10-069 | EC130 B4 | CABIN BACK WALL ATTACHMENT RINGS | 130-203104 | 13-Aug-12 | 1 |
| ICA-ECL-195 | O-LSH10-181 | EC120 | INTERIOR MODIFICATIONS | 120-701634 | 10-Jun-10 | 0 |
| ICA-ECL-196 | O-LSH10-113 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701764 | 05-May-10 | 0 |
| ICA-ECL-197 | O-LSH10-190 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701774 | 24-Jun-10 | 0 |
| ICA-ECL-199 | O-LSH10-203 | EC120B | INTERIOR MODIFICATIONS | 120-701654 | 19-Jul-10 | 0 |
| ICA-ECL-200 | O-LSH10-243 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701664 | 20-Aug-10 | 0 |
| ICA-ECL-201 | SH12-53 | EC130B4 | SECOND BATTERY INSTALLATION | 130-700234 | 01-Oct-12 | 5 |
| ICA-ECL-202 | O-LSH10-259 | EC130 B4 | INTERIOR MODIFICATIONS | 130-701674 | 17-Sep-10 | 0 |
| ICA-ECL-203 | SH12-9 | EC120 | RH DOOR INSTALLATION | 120-200014 | 27-Feb-13 | 1 |
| ICA-ECL-204 | SH12-10 | EC130 B4 | RH DOOR INSTALLATION | 120-200014 | 27-Feb-13 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|----------------|-----------|--|-------------|-------------|------|
| ICA-ECL-205 | O-LSH10-291 | EC120B | INTERIOR MODIFICATIONS | 120-701644 | 05-Nov-10 | 0 |
| ICA-ECL-206 | O-LSH10-308 | EC120B | FLIR U8500 SYSTEM INSTALLATION | 120-901864 | 30-Nov-10 | 2 |
| ICA-ECL-207 | SH97-33 | AS350/355 | REAR CARGO DOOR HINGE AND LATCH MODIFICATION | 350-201064 | 15-Oct-2013 | 2 |
| ICA-ECL-208 | O-LSH10-309 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701794 | 02-Apr-12 | 2 |
| ICA-ECL-209 | SH11-11 | EC135 | CARGO COMPARTMENT MODS | 135-200304 | 13-Apr-11 | 0 |
| ICA-ECL-211 | O-LSH-11-052 | EC135 | INTERIOR MODIFICATIONS | 135-701614 | 04-Apr-11 | 0 |
| ICA-ECL-212 | O-LSH-11-066 | EC135 | FLIR INSTALLATION | 135-901814 | 21-Apr-11 | 0 |
| ICA-ECL-213 | O-LSH-11-065 | EC135 | SX-16 INSTALLATION | 135-901214 | 21-Apr-11 | 0 |
| ICA-ECL-214 | O-LSH-11-070 | EC135 | VIDOE DOWNLINK | 135-902714 | 15-Apr-11 | 0 |
| ICA-ECL-215 | O-LSH-11-069 | EC135 | DOOR OPEN WARNING | 135-901014 | 15-Apr-11 | 0 |
| ICA-ECL-216 | O-LSH-11-073/D | AS350 B2 | COMM NAV SYSTEM | 350-880974 | 20-Apr-11 | 1 |
| ICA-ECL-217 | O-LSH-11-059 | AS355 NP | INTERIOR MODIFICATIONS | 355-701614 | 07-Apr-11 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|--------------------------|--------------------|-------------|-------------|
| ICA-ECL-218 | O-LSH-11-053 | AS350 B2 | INTERIOR MODIFICATIONS | 350-701784 | 05-Apr-11 | 0 |
| ICA-ECL-219 | O-LSH-11-097 | AS350 B3 | INTERIOR MODIFICATIONS | 350-702234 | 18-May-11 | 1 |
| ICA-ECL-220 | O-LSH-11-087 | AS350 B3 | INTERIOR MODIFICATIONS | 350-701804 | 03-May-11 | 0 |
| ICA-ECL-221 | O-LSH-11-081/D | AS350 B3 | BMS DOWNLINK | 350-902994 | 10-May-11 | 1 |
| ICA-ECL-222 | O-LSH-11-074/D | EC135 | PULSE LIGHT INSTALLATION | 135-902414 | 21-Apr-11 | 1 |
| ICA-ECL-223 | SH11-35 | EC130 B4 | ADJUSTABLE GLARE SHIELD | 130-885114 | 17-Jun-13 | 1 |
| ICA-ECL-225 | O-LSH-11-064/D | EC130 B4 | INTERIOR MODIFICATIONS | 130-701684 | 19-Apr-11 | 0 |
| ICA-ECL-227 | O-LSH-11-091/D | AS350 B2 | INTERIOR MODIFICATIONS | 350-702244 | 10-May-11 | 0 |
| ICA-ECL-228 | O-LSH-11-073/D | AS350 B3 | INTERIOR MODIFICATIONS | 350-701034 | 20-May-11 | 0 |
| ICA-ECL-229 | O-LSH-11-124 | AS350 B3 | INTERIOR MODIFICATIONS | 350-702254 | 30-Jun-11 | 0 |
| ICA-ECL-230 | O-LSH-11-134 | AS350 B2 | INTERIOR MODIFICATIONS | 350-702224 | 15-Jul-11 | 1 |
| ICA-ECL-232 | O-LSH-11-127 | AS350 B2 | INTERIOR MODIFICATIONS | 350-702264 | 06-Jul-11 | 1 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|---------------------|--------------------------------|---------------------------|-------------|-------------|
| ICA-ECL-233 | SH12-52 | AS350 | CABLE CUTTER INSTALLATION | 350-252004 | 01-Oct-12 | 2 |
| ICA-ECL-234 | O-LSH11-111 | AS350B3 | ADJUSTABLE GLARE SHIELD | ESK-1457 | 17-Jun-11 | 0 |
| ICA-ECL-236 | O-LSH11-172 | AS350 B3 | INTERIOR MODIFICATION | 350-702274 | 03-Oct-11 | 0 |
| ICA-ECL-237 | SH96-126 | AS350/355/ EC130 | BLADE TIE DOWN PROVISIONS | 350-700414/ 130-700414 | 14-Jun-12 | 1 |
| ICA-ECL-238 | O-LSH11-167 | AS350 B3 | INTERIOR MODIFICATION | 350-702284 | 26-Sep-11 | 0 |
| ICA-ECL-241 | O-LSH11-220 | EC130 B4 | INTERIOR MODIFICATION | 130-701694 | 08-Dec-11 | 0 |
| ICA-ECL-242 | SH12-28 | AS350 | STANDARD INTERIOR MODIFICATION | 350-701904 | 05-Nov-12 | 3 |
| ICA-ECL-243 | SH12-28 | AS350 | STANDARD INTERIOR MODIFICATION | 350-701814 | 11-Apr-12 | 1 |
| ICA-ECL-244 | SH12-28 | AS350 | STANDARD INTERIOR MODIFICATION | 350-701074 | 11-Apr-12 | 1 |
| ICA-ECL-245 | SH12-28 | AS350 | STANDARD INTERIOR MODIFICATION | 350-701044 | 05-Nov-12 | 2 |
| ICA-ECL-246 | O-LSH12-010 | AS350 B3 | INTERIOR MODIFICATION | 350-702314 | 20-Jan-12 | 0 |
| ICA-ECL-247 | O-LSH12-033/D | AS350 B3 | INTERIOR MODIFICATION | 350-702294 | 09-Mar-12 | 0 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|---------------|-------------|---------------------|---------------------------------------|-------------|-----------|------|
| ICA-ECL-248 | O-LSH12-046 | AS350 B2 | INTERIOR MODIFICATION | 350-702334 | 08-Mar-12 | 1 |
| ICA-ECL-249 | O-LSH12-054 | AS350 B3 | INTERIOR MODIFICATION | 350-702304 | 21-Mar-12 | 1 |
| ICA-ECL-250 | SH12-12 | EC130 B4 | REAR DRIVE SHAFT END CAP INSTALLATION | 130-300014 | 22-Feb-12 | 0 |
| ICA-ECL-251 | SH12-16 | AS350 B3 | OPERATION WITH SANDFILTER REMOVED | 350-800044 | 13-Mar-12 | 2 |
| ICA-ECL-252 | O-LSH12-079 | AS350 B3 | INTERIOR MODIFICATION | 350-702324 | 24-Apr-12 | 0 |
| ICA-ECL-253 | O-LSH12-086 | AS350 B3 | INTERIOR MODIFICATION | 350-702354 | 14-May-12 | 1 |
| ICA-ECL-255 | O-LSH12-189 | AS350 B3 | COMM NAV SYSTEM | 350-881014 | 10-Dec-12 | 0 |
| ICA-ECL-256 | O-LSH12-096 | EC130 B4 | INTERIOR MODIFICATION | 130-701714 | 22-May-12 | 1 |
| ICA-ECL-257 | O-LSH12-099 | EC130 B4 | INTERIOR MODIFICATION | 130-701704 | 25-May-12 | 1 |
| ICA-ECL-258 | O-LSH12-126 | AS350 B3 | INTERIOR MODIFICATION | 350-702384 | 18-Jun-12 | 1 |
| ICA-ECL-259 | SH12-28 | AS350 | STANDARD INTERIOR MODIFICATION | 350-702204 | 05-Nov-12 | 1 |
| ICA-ECL-260 | SH96-39 | AS350 BA, B2, B3 | TWO PLACE FORWARD PASSENGER SEAT | 350-200624 | 18-Dec-13 | 2 |



| Report Number | STC Number | Model | Report Title | Part Number | Date | Rev. |
|----------------------|-------------------|--------------|-----------------------|--------------------|-------------|-------------|
| ICA-ECL-261 | O-LSH12-177 | AS350 B3e | INTERIOR MODIFICATION | 350-702364 | 01-Nov-12 | 1 |
| ICA-ECL-262 | O-LSH12-168/D | AS350 B2 | INTERIOR MODIFICATION | 350-702344 | 31-Oct-12 | 0 |
| ICA-ECL-266 | O-LSH13-041 | AS350 B2 | INTERIOR MODIFICATION | 350-702374 | 21-Mar-13 | 0 |
| ICA-ECL-267 | O-LSH13-038 | EC130 B4 | INTERIOR MODIFICATION | 130-701724 | 15-Mar-13 | 1 |
| ICA-ECL-268 | O-LSH13-123 | EC135 | INTERIOR MODIFICATION | 135-701624 | 29-Aug-13 | 0 |
| ICA-ECL-271 | O-LSH13-150 | EC120 B | INTERIOR MODIFICATION | 120-701664 | 21-Nov-13 | 1 |
| ICA-ECL-272 | O-LSH13-161 | EC135 | INTERIOR MODIFICATION | 135-701634 | 12-Dec-13 | 1 |