

### MAINTENANCE MANUAL SUPPLEMENTS

| Report Number | STC Number   | Model            | Report Title                        | Part Number              | Date      | Rev.                               |
|---------------|--------------|------------------|-------------------------------------|--------------------------|-----------|------------------------------------|
| MMS-ECL-003   |              | AS350 BA, B2, B3 | AIRFRAME FUEL FILTER                | 350-600004               |           | <b>Superseded with ICA-ECL-130</b> |
| MMS-ECL-006   | SH96-31      | AS355            | BATTERY POWER SYSTEM RELOCATION     | 350-700214/324           |           | <b>Superseded with ICA-ECL-125</b> |
| MMS-ECL-023   |              | AS350/355        | SETTLING PROTECTORS                 | 350-500214               |           | <b>Superseded with ICA-ECL-124</b> |
| MMS-ECL-024   |              | AS350/355        | AIRBORNE SATELLITE TELEPHONE SYSTEM | 350-901704               | 24-May-00 | 1                                  |
| MMS-ECL-028   | SH96-129     | AS350/355        | STIRRUP STEPS INSTALLATION          | 350-201604               | 19-Apr-00 | 0                                  |
| MMS-ECL-029   | SH98-44      | AS350/355        | RAIL STEPS                          | 350-500194/204           | 11-Jul-00 | 0                                  |
| MMS-ECL-032   |              | AS350            | PA / SIREN SYSTEM                   | 350-888594               | 27-Jul-00 | 0                                  |
| MMS-ECL-033   | SH97-36      | AS350            | COWLING MAINTENANCE STEPS           | 350-200094/104           | 26-May-00 | 0                                  |
| MMS-ECL-035   | SH00-1       | AS350            | HIGH VISIBILITY DOOR                | 350-202014               | 30-Aug-04 | 2                                  |
| MMS-ECL-036   |              | AS350            | LEFT SIDE PILOT CONFIGURATION       | 350-400004/74            |           | <b>Superseded with ICA-ECL-168</b> |
| MMS-ECL-037   |              | AS350/355        | SETTLING PROTECTORS                 | 350-400164<br>120-500214 |           | <b>Superseded with ICA-ECL-026</b> |
| MMS-ECL-040   | SH96-115     | AS350            | FIREWALL REINFORCEMENT              | 350-601014               | 30-Aug-04 | 1                                  |
| MMS-ECL-101   | O-LSH04-078  | AS350 B3         | MISSION EQUIPMENT MODIFICATIONS     | 350-902804/904           | 19-May-05 | 3                                  |
| MMS-ECL-102   | O-LSH08-186D | AS350 B3         | FLIR U8000/U8500 SYSTEM             | 350-903544               | 28-Aug-08 | 0                                  |
| MMS-ECL-103   | O-LSH07-049D | AS350 B3         | AUTOPILOT INTERFACE                 | 350-401144               | 28-Aug-08 | 0                                  |

|             |              |          |                       |            |           |   |
|-------------|--------------|----------|-----------------------|------------|-----------|---|
| MMS-ECL-104 | O-LSH08-188D | AS350 B3 | COMM NAV              | 350-880914 | 28-Aug-08 | 0 |
| MMS-ECL-105 | O-LSH08-187D | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902934 | 28-Aug-08 | 0 |
| MMS-ECL-106 | O-LSH09-200D | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902974 | 22-Jun-09 | 0 |
| MMS-ECL-107 |              | AS350 B3 | VIDEO DOWNLINK SYSTEM | 350-902984 | 03-Jul-09 | 0 |
| MMS-ECL-108 | O-LSH07-051D | AS350 B3 | FLIR U8500            | 350-903584 | 22-Jun-09 | 0 |