## Department of Transport

## Supplemental Type Certificate

This approval is issued to:

**Eurocopter Canada Limited** 

Number: SH02-45

Issue No.:

**Approval Date:** 

Issue Date:

December 23, 2002

December 23, 2002

P.O. Box 250

Fort Erie, ONTARIO L2A 5M9 CANADA

1100 Gilmore Road

Responsible Office:

Ontario

Aircraft/Engine Type or Model:

Eurocopter EC130 B4

**Canadian Type Certificate or Equivalent:** 

H-83

**Description of Type Design Change:** 

Litter Kit Installation

(130-200034)

Installation/Operating Data, **Required Equipment and Limitations:** 

- 1. Configuration must be in accordance with Eurocopter Canada Limited Master Drawing List 02/016, Issue A, Transport Canada approved December 23, 2002, or later transport Canada approved revisions.
- 2. Installation must be performed in accordance with Installation Procedure No IP-ECL-106 revision 0, Transport Canada approved December 23, 2002, or later Transport Canada approved revisions.
- 3. Operation must be in accordance with Eurocopter Canada Limited Flight Manual Supplement No. FMS-ECL-105 revision 0, Transport Canada approved December 23, 2002, or later Transport Canada approved revisions.

-See Continuation Sheet-



Conditions: This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this modification, the installer shall establish that the interrelationship between this change and any other modification(s) incorporated will not adversely affect the airworthiness of the modified product.

> Senior Engineer, Aircraft Certification For Minister of Transport

> > Canadä

## (Continuation Sheet)

Number: SH02-45 Issue 1

## NOTE: THIS ADDENDUM SHALL REMAIN PART OF THE CERTIFICATE REFERRED TO THEREIN.

- 4. The Rotorcraft must be maintained in accordance with Eurocopter Canada Limited Instructions for Continued Airworthiness document No ICA-ECL-119, revision 0, Transport Canada accepted December 23, 2002, or later Transport Canada accepted revisions.
- 5. Aircraft must be configured with LH Side Flight Controls in accordance with EC SB 25-028.
- 6. The Litter Kit Installation is not compatible with Dual Controls.

-END-