



| Report Number | STC Number | Model    | Report Title                            | Part Number               | Date      | Rev. |
|---------------|------------|----------|-----------------------------------------|---------------------------|-----------|------|
| ICA-ECL-025   |            | AS350 B3 | COMM NAV SYSTEM                         | 350-870854                | 17-Feb-04 | 0    |
| ICA-ECL-026   | SH00-30    | EC120B   | SETTLING PROTECTORS                     | 120-500214-02             | 19-May-05 | 3    |
| ICA-ECL-029   |            | EC120B   | COMM NAV SYSTEM STANDARD PACKAGE        |                           | 13-Sep-00 | 1    |
| ICA-ECL-030   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870484                | 13-Sep-00 | 1    |
| ICA-ECL-031   |            | EC120B   | COMM NAV INSTALLATION, STANDARD PACKAGE | 120-870494                | 13-Sep-00 | 1    |
| ICA-ECL-032   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870444                | 13-Sep-00 | 1    |
| ICA-ECL-033   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870544                | 13-Sep-00 | 1    |
| ICA-ECL-034   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870454,<br>120-870504 | 13-Sep-00 | 1    |
| ICA-ECL-035   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870654                | 13-Sep-00 | 1    |
| ICA-ECL-036   |            | EC120B   | COMM NAV INSTALLATION, STANDARD PACKAGE | 120-870404                | 13-Sep-00 | 1    |
| ICA-ECL-037   |            | EC120B   | DIRECTIONAL GYRO                        | 120-870274                | 29-Apr-02 | 2    |
| ICA-ECL-038   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870074                | 13-Sep-00 | 1    |
| ICA-ECL-039   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870114                | 13-Sep-00 | 1    |
| ICA-ECL-040   |            | EC120B   | COM NAV INSTALLATION, STANDARD PACKAGE  | 120-870094                | 13-Sep-00 | 1    |



| Report Number | STC Number | Model  | Report Title                                             | Part Number | Date      | Rev. |
|---------------|------------|--------|----------------------------------------------------------|-------------|-----------|------|
| ICA-ECL-041   |            | EC120B | SLASS SYSTEM                                             |             | 25-Jun-01 | 0    |
| ICA-ECL-042A  |            | EC120B | FLIR SYSTEM                                              | 120-901014  | 21-Dec-01 | 4    |
| ICA-ECL-100   |            | EC120B | PA/SPEAKER                                               | 120-888414  | 10-Jul-03 | 2    |
| ICA-ECL-101   |            | EC120B | GPS NAVIGATIONSYSTEM                                     | 120-870894  | 29-Apr-02 | 0    |
| ICA-ECL-102   |            | EC120B | BASIC KY-196 VHF COMM 1 VHF TRANSCEIVER SYSTEM           | 120-870484  | 29-Apr-02 | 0    |
| ICA-ECL-103   |            | EC120B | BASIC AND ENHANCED 4000-10A ELT SYSTEM                   | 120-870914  | 29-Apr-02 | 0    |
| ICA-ECL-104   |            | EC120B | BASIC AND ENHANCED DIGITAL CLOCK                         | 120-870934  | 29-Apr-02 | 0    |
| ICA-ECL-105   |            | EC120B | ENHANCED KT-76C TRANSPONDER SYSTEM                       | 120-870944  | 29-Apr-02 | 0    |
| ICA-ECL-106   |            | EC120B | BASIC KT-76A TRANSPONDER SYSTEM                          | 120-870454  | 29-Apr-02 | 0    |
| ICA-ECL-107   |            | EC120B | BASIC AND ENHANCED 200HM ELT SYSTEM                      | 120-870924  | 29-Apr-02 | 0    |
| ICA-ECL-108   |            | EC120B | COMM/NAV SYSTEM STANDARD PACKAGE TC TYPE CERTIFICATE     |             | 04-Dec-01 | 0    |
| ICA-ECL-109   |            | EC120B | STANDARD PACKAGE, BASIC AND ENHANCED AMS-42 AUDIO SYSTEM | 120-870904  | 02-May-00 | 0    |



| Report Number | STC Number   | Model     | Report Title                             | Part Number                              | Date      | Rev. |
|---------------|--------------|-----------|------------------------------------------|------------------------------------------|-----------|------|
| ICA-ECL-110   |              | EC120B    | STANDARD PACKAGE, ENHANCED COMM 1 SYSTEM | 120-870534                               | 02-May-02 | 0    |
| ICA-ECL-111   |              | EC130 B4  | AFT RH CABIN DOOR RETROFIT               | 130-202424                               | 10-Jul-03 | 1    |
| ICA-ECL-112   | SH02-38      | EC130 B4  | COWLING MAINTENANCE STEPS                | 130-200094/104                           | 22-Nov-02 | 0    |
| ICA-ECL-114   | O-LSH02-057  | EC 120B   | COMM NAV EQUIPMENT                       | 120-889654,<br>120-883174,<br>120-884774 | 11-Oct-02 | 0    |
| ICA-ECL-116A  | O-LSH02-672D | EC120B    | FLIR SYSTEM                              | 120-901064                               | 20-Nov-02 | 2    |
| ICA-ECL-117   | SH02-39      | EC120B    | IMPROVED HEATING SYSTEM                  | 120-701014                               | 10-May-13 | 7    |
| ICA-ECL-118   | SH02-42      | EC130 B4  | AIRFRAME FUEL FILTER                     | 130-600004                               | 21-Jul-15 | 9    |
| ICA-ECL-119   | SH02-45      | EC130 B4  | LITTER KIT FOR 7 & 8 PLACE               | 130-200034                               | 09-Jun-05 | 3    |
| ICA-ECL-120   | SH02-44      | EC130 B4  | CARGO PODS                               | 130-200814                               | 30-Dec-02 | 0    |
| ICA-ECL-122   | SH03-15      | EC120B    | SPECTROLAB SX-16 NIGHTSUN SEARCHLIGHT    | 120-901234                               | 20-Mar-06 | 2    |
| ICA-ECL-123   | SH03-33      | EC130 B4  | CARGO POD INSTALLATION                   | 130-201024                               | 11-Apr-13 | 4    |
| ICA-ECL-124   | SH01-22      | AS350/355 | SETTLING PROTECTORS                      | 120-500214-01                            | 19-May-05 | 1    |

Instructions for Continued Airworthiness

Last updated: 9 November 2020



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b>           | <b>Report Title</b>                  | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|------------------------|--------------------------------------|--------------------|-------------|-------------|
| ICA-ECL-125          | SH96-31           | AS350/355              | BATTERY RELOCATION                   | 350-700324         | 24-Oct-13   | 12          |
| ICA-ECL-126          | SH96-32           | AS350                  | RIGHT HAND LITTER KIT                | 350-200144         | 10-Mar-17   | 4           |
| ICA-ECL-127          | SH94-29           | AS350/355              | LEFT HAND LITTER KIT                 | 350-200034         | 11-Jun-20   | 6           |
| ICA-ECL-128          | SH04-28           | EC130 B4               | AFT BENCH SEAT                       | 130-700614         | 19-Feb-08   | 4           |
| ICA-ECL-129          | SH02-42           | AS350 B3               | AIRFRAME FUEL FILTER                 | 350-600024         | 21-Jul-15   | 7           |
| ICA-ECL-130          | SH94-31           | AS350 B, BA,<br>B1, B2 | AIRFRAME FUEL FILTER                 | 350-600004         | 09-Apr-13   | 4           |
| ICA-ECL-131          | SH96-61           | AS350/355              | CARGO MIRROR INSTALLATION            | 350-200254/64      | 16-May-18   | 1           |
| ICA-ECL-132          | SH96-114          | AS350                  | BELLY-MOUNTED ANTI-COLLISION LIGHT   | 350-900624         | 10-Mar-08   | 1           |
| ICA-ECL-133          | SH05-18           | AS350                  | HIGH VISIBILITY DOOR (SHORT)         | 350-202414         | 18-Apr-13   | 2           |
| ICA-ECL-134          | SH04-53           | EC130 B4               | OPERATION WITH SANDFILTER REMOVED    | 130-800034         | 30-Nov-04   | 0           |
| ICA-ECL-136          | SH05-39           | EC130 B4               | WIRE STRIKE PROTECTION SYSTEM        | 130-300214         | 08-Sep-05   | 0           |
| ICA-ECL-137          | SH05-47           | EC120B                 | FLIR U8000/U8500 SYSTEM INSTALLATION | 120-901814         | 04-Dec-08   | 1           |



| Report Number | STC Number  | Model     | Report Title                                | Part Number            | Date      | Rev. |
|---------------|-------------|-----------|---------------------------------------------|------------------------|-----------|------|
| ICA-ECL-138   | O-LSH05-310 | EC120B    | VIDEO DOWNLINK SYSTEM                       | 120-902904             | 19-May-06 | 1    |
| ICA-ECL-139   | SH06-11     | EC130 B4  | HEAVY DUTY BATTERY INSTALLATION             | 130-700214             | 20-Mar-06 | 0    |
| ICA-ECL-140   | SH06-12     | AS350/355 | ENLARGED VERTICAL REFERENCE WINDOW          | 350/355-201154         | 28-Jan-15 | 5    |
| ICA-ECL-141   | SH97-34     | AS350/355 | FORWARD OPENING REAR CARGO DOOR             | 350-201014, 130-201004 | 30-May-13 | 5    |
| ICA-ECL-143   | SH06-28     | AS350     | POP IMAGING SYSTEM                          | 350-903214             | 15-Jun-07 | 2    |
| ICA-ECL-144   |             | AS350 B3  | VIDEO DOWNLINK SYSTEM                       | 350-902924             | 19-Feb-06 | 0    |
| ICA-ECL-145   |             | AS350 B3  | FLIR U7000 SYSTEM INSTALLATION              | 350-903504             | 21-Feb-06 | 0    |
| ICA-ECL-147   | SH07-50     | EC130 B4  | COMM NAV SYSTEM MODIFICATION                | 130-883004             | 27-Aug-08 | 2    |
| ICA-ECL-148   | SH07-48     | AS350 B3  | COMM NAV SYSTEM MODIFICATION                | 350-880934             | 16-Apr-10 | 3    |
| ICA-ECL-149   | SH05-16     | AS350 B3  | COMM NAV SYSTEM MODIFICATION                | 350-880884             | 12-May-08 | 0    |
| ICA-ECL-150   | SH99-205    | AS350     | PUBLIC ADDRESS / SIREN SYSTEM               | 350-888594             | 30-Nov-07 | 0    |
| ICA-ECL-151   |             | EC120 B   | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880214             | 09-Jan-13 | 0    |



| Report Number | STC Number   | Model     | Report Title                                | Part Number     | Date       | Rev. |
|---------------|--------------|-----------|---------------------------------------------|-----------------|------------|------|
| ICA-ECL-152   | O-LSH98-107  | AS350 B3  | SECURITY BARRIER                            | 350-702014      | 03-Feb-10  | 1    |
| ICA-ECL-153   | O-LSH07-020  | AS350 B3  | MISSION EQUIPMENT RACK                      | 350-902824      | 25-Apr-08  | 0    |
| ICA-ECL-154   | O-LSH07-015  | AS350 B3  | ALTERNATIVE LIGHTING SYSTEM                 | 350-902524      | 29-Aug-08  | 1    |
| ICA-ECL-155   | O-LSH08-283D | EC120B    | ALTERNATE LIGHTING                          | 120-903214      | 11-Dec-08  | 0    |
| ICA-ECL-156   | O-LSH08-282  | EC120B    | VIDEO DOWNLINK SYSTEM                       | 120-902934      | 12-Dec-08  | 1    |
| ICA-ECL-157   | O-LSH08-288  | AS350 B3  | COMM NAV SYSTEM                             | 350-880944      | 19-Dec-08  | 0    |
| ICA-ECL-158   | O-LSH08-288  | AS350 B3  | LH PILOT CONFIGURATION                      | 350-400164      | 15-Jul-09  | 1    |
| ICA-ECL-161   |              | AS350 B3  | TWO PLACE FORWARD PASSENGER SEAT            | 350-200624      | 19-Dec-08  | 0    |
| ICA-ECL-162   | O-LSH08-298  | EC 130 B4 | DUAL BATTERY INSTALLATION                   | 350 A62 2537 00 | 17-June-13 | 3    |
| ICA-ECL-163   |              | EC120 B   | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880204      | 09-Jan-13  | 0    |
| ICA-ECL-164   | O-LSH09-081  | AS350 B2  | COMM NAV SYSTEM                             | 350-880954      | 21-Apr-09  | 1    |
| ICA-ECL-165   | SH09-11      | AS350 B2  | DUAL SAGEM ICDS-6 INSTALLATION              | 350-873044      | 04-Nov-09  | 1    |



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>    | <b>Part Number</b>           | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|------------------------|------------------------------|-------------|-------------|
| ICA-ECL-166          | O-LSH09-127       | AS350 B2     | INTERIOR               | 350-701614                   | 27-Apr-09   | 0           |
| ICA-ECL-167          | O-LSH09-128       | AS350 B3     | INTERIOR MODIFICATIONS | 350-701624                   | 14-Sep-09   | 2           |
| ICA-ECL-168          | SH96-32           | AS350        | LEFT SIDE PILOT        | 350-400004/74,<br>350-400164 | 25-Oct-13   | 6           |
| ICA-ECL-169          | O-LSH09-123       | EC130 B4     | INTERIOR MODIFICATIONS | 130-701614                   | 14-Nov-13   | 7           |
| ICA-ECL-170          | O-LSH09-245       | EC120B       | DUAL SAGEM ICDS-6A     | 120-872744                   | 31-Jul-09   | 2           |
| ICA-ECL-171          | O-LSH09-247       | EC120B       | COMM NAV SYSTEM        | 120-880284                   | 31-Jul-09   | 1           |
| ICA-ECL-172          | O-LSH09-142       | EC130 B4     | INTERIOR MODIFICATIONS | 130-701624                   | 11-May-09   | 0           |
| ICA-ECL-173          | O-LSH09-141       | AS350 B3     | INTERIOR MODIFICATIONS | 350-701634                   | 06-May-09   | 0           |
| ICA-ECL-174          | O-LSH09-145       | EC130 B4     | INTERIOR MODIFICATIONS | 130-701634                   | 08-Sep-09   | 1           |
| ICA-ECL-175          | O-LSH09-224D      | EC120B       | INTERIOR MODIFICATIONS | 120-701614                   | 22-Jul-09   | 1           |
| ICA-ECL-177          | O-LSH09-202       | EC120B       | INTERIOR MODIFICATIONS | 120-701624                   | 25-Jun-09   | 0           |
| ICA-ECL-178          | O-LSH09-263D      | AS350 B3     | INTERIOR MODIFICATIONS | 350-701644                   | 18-Aug-09   | 1           |



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>    | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|------------------------|--------------------|-------------|-------------|
| ICA-ECL-179          | O-LSH09-266D      | EC130 B4     | INTERIOR MODIFICATIONS | 130-701644         | 18-Sep-09   | 1           |
| ICA-ECL-180          | O-LSH09-264D      | AS350        | INTERIOR MODIFICATIONS | 350-701684         | 27-Aug-09   | 0           |
| ICA-ECL-181          | O-LSH09-354       | AS350 B3     | INTERIOR MODIFICATIONS | 350-701664         | 24-Nov-09   | 0           |
| ICA-ECL-182          | O-LSH09-0342      | AS350 B2     | INTERIOR MODIFICATIONS | 350-701654         | 04-Nov-09   | 0           |
| ICA-ECL-183          | O-LSH09-0343      | AS350 B3     | INTERIOR MODIFICATIONS | 350-701674         | 04-Nov-09   | 0           |
| ICA-ECL-184          | O-LSH09-379       | AS350        | INTERIOR MODIFICATIONS | 350-701694         | 07-Dec-09   | 0           |
| ICA-ECL-185          | O-LSH09-355       | AS350 B3     | INTERIOR MODIFICATIONS | 350-701704         | 29-Jul-10   | 1           |
| ICA-ECL-186          | O-LSH10-103       | AS350        | INTERIOR MODIFICATIONS | 350-701714         | 27-Apr-10   | 1           |
| ICA-ECL-187          | O-LSH10-019       | AS350 B3     | INTERIOR MODIFICATIONS | 350-701724         | 25-Jan-10   | 0           |
| ICA-ECL-188          | O-LSH10-104       | AS350 B3     | INTERIOR MODIFICATIONS | 350-701744         | 26-Apr-10   | 0           |
| ICA-ECL-189          | O-LSH10-091       | AS350 B2     | INTERIOR MODIFICATIONS | 350-701754         | 13-Apr-10   | 1           |
| ICA-ECL-190          | O-LSH10-102       | AS350 B2     | INTERIOR MODIFICATIONS | 350-701734         | 14-Jan-11   | 3           |





| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>              | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|----------------------------------|--------------------|-------------|-------------|
| ICA-ECL-191          | SH10-20           | EC130 B4     | OPERATION WITH DOORS REMOVED     |                    | 18-Dec-13   | 3           |
| ICA-ECL-192          | O-LSH10-114       | EC130 B4     | INTERIOR MODIFICATIONS           | 130-701654         | 05-May-10   | 0           |
| ICA-ECL-194          | O-LSH10-069       | EC130 B4     | CABIN BACK WALL ATTACHMENT RINGS | 130-203104         | 13-Aug-12   | 1           |
| ICA-ECL-195          | O-LSH10-181       | EC120        | INTERIOR MODIFICATIONS           | 120-701634         | 10-Jun-10   | 0           |
| ICA-ECL-196          | O-LSH10-113       | AS350 B3     | INTERIOR MODIFICATIONS           | 350-701764         | 05-May-10   | 0           |
| ICA-ECL-197          | O-LSH10-190       | AS350 B2     | INTERIOR MODIFICATIONS           | 350-701774         | 24-Jun-10   | 0           |
| ICA-ECL-199          | O-LSH10-203       | EC120B       | INTERIOR MODIFICATIONS           | 120-701654         | 19-Jul-10   | 0           |
| ICA-ECL-200          | O-LSH10-243       | EC130 B4     | INTERIOR MODIFICATIONS           | 130-701664         | 20-Aug-10   | 0           |
| ICA-ECL-201          | SH12-53           | EC130B4      | SECOND BATTERY INSTALLATION      | 130-700234         | 01-Oct-12   | 5           |
| ICA-ECL-202          | O-LSH10-259       | EC130 B4     | INTERIOR MODIFICATIONS           | 130-701674         | 17-Sep-10   | 0           |
| ICA-ECL-203          | SH12-9            | EC120        | RH DOOR INSTALLATION             | 120-200014         | 27-Feb-13   | 1           |
| ICA-ECL-204          | SH12-10           | EC130 B4     | RH DOOR INSTALLATION             | 120-200014         | 27-Feb-13   | 1           |



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>                          | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|----------------------------------------------|--------------------|-------------|-------------|
| ICA-ECL-205          | O-LSH10-291       | EC120B       | INTERIOR MODIFICATIONS                       | 120-701644         | 05-Nov-10   | 0           |
| ICA-ECL-206          | O-LSH10-308       | EC120B       | FLIR U8500 SYSTEM INSTALLATION               | 120-901864         | 30-Nov-10   | 2           |
| ICA-ECL-207          | SH97-33           | AS350/355    | REAR CARGO DOOR HINGE AND LATCH MODIFICATION | 350-201064         | 15-Oct-2013 | 2           |
| ICA-ECL-208          | O-LSH10-309       | AS350 B3     | INTERIOR MODIFICATIONS                       | 350-701794         | 02-Apr-12   | 2           |
| ICA-ECL-209          | SH11-11           | EC135        | CARGO COMPARTMENT MODS                       | 135-200304         | 13-Apr-11   | 0           |
| ICA-ECL-211          | O-LSH-11-052      | EC135        | INTERIOR MODIFICATIONS                       | 135-701614         | 04-Apr-11   | 0           |
| ICA-ECL-212          | O-LSH-11-066      | EC135        | FLIR INSTALLATION                            | 135-901814         | 21-Apr-11   | 0           |
| ICA-ECL-213          | O-LSH-11-065      | EC135        | SX-16 INSTALLATION                           | 135-901214         | 21-Apr-11   | 0           |
| ICA-ECL-214          | O-LSH-11-070      | EC135        | VIDOE DOWNLINK                               | 135-902714         | 15-Apr-11   | 0           |
| ICA-ECL-215          | O-LSH-11-069      | EC135        | DOOR OPEN WARNING                            | 135-901014         | 15-Apr-11   | 0           |
| ICA-ECL-216          | O-LSH-11-073/D    | AS350 B2     | COMM NAV SYSTEM                              | 350-880974         | 20-Apr-11   | 1           |
| ICA-ECL-217          | O-LSH-11-059      | AS355 NP     | INTERIOR MODIFICATIONS                       | 355-701614         | 07-Apr-11   | 0           |



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>      | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|--------------------------|--------------------|-------------|-------------|
| ICA-ECL-218          | O-LSH-11-053      | AS350 B2     | INTERIOR MODIFICATIONS   | 350-701784         | 05-Apr-11   | 0           |
| ICA-ECL-219          | O-LSH-11-097      | AS350 B3     | INTERIOR MODIFICATIONS   | 350-702234         | 18-May-11   | 1           |
| ICA-ECL-220          | O-LSH-11-087      | AS350 B3     | INTERIOR MODIFICATIONS   | 350-701804         | 03-May-11   | 0           |
| ICA-ECL-221          | O-LSH-11-081/D    | AS350 B3     | BMS DOWNLINK             | 350-902994         | 10-May-11   | 1           |
| ICA-ECL-222          | O-LSH-11-074/D    | EC135        | PULSE LIGHT INSTALLATION | 135-902414         | 21-Apr-11   | 1           |
| ICA-ECL-223          | SH11-35           | EC130 B4     | ADJUSTABLE GLARE SHIELD  | 130-885114         | 17-Jun-13   | 1           |
| ICA-ECL-225          | O-LSH-11-064/D    | EC130 B4     | INTERIOR MODIFICATIONS   | 130-701684         | 19-Apr-11   | 0           |
| ICA-ECL-227          | O-LSH-11-091/D    | AS350 B2     | INTERIOR MODIFICATIONS   | 350-702244         | 10-May-11   | 0           |
| ICA-ECL-228          | O-LSH-11-073/D    | AS350 B3     | INTERIOR MODIFICATIONS   | 350-701034         | 20-May-11   | 0           |
| ICA-ECL-229          | O-LSH-11-124      | AS350 B3     | INTERIOR MODIFICATIONS   | 350-702254         | 30-Jun-11   | 0           |
| ICA-ECL-230          | O-LSH-11-134      | AS350 B2     | INTERIOR MODIFICATIONS   | 350-702224         | 15-Jul-11   | 1           |
| ICA-ECL-232          | O-LSH-11-127      | AS350 B2     | INTERIOR MODIFICATIONS   | 350-702264         | 06-Jul-11   | 1           |



| Report Number | STC Number  | Model               | Report Title                     | Part Number                              | Date      | Rev. |
|---------------|-------------|---------------------|----------------------------------|------------------------------------------|-----------|------|
| ICA-ECL-233   | SH12-52     | AS350               | CABLE CUTTER INSTALLATION        | 350-252004                               | 05-Dec-14 | 3    |
| ICA-ECL-234   | O-LSH11-111 | AS350B3             | ADJUSTABLE GLARE SHIELD          | ESK-1457                                 | 17-Jun-11 | 0    |
| ICA-ECL-235   | SH98-43     | AS350/355           | REAR CROSS TUBE MAINTENANCE STEP | 350-500604                               | 11-Dec-14 | 1    |
| ICA-ECL-236   | O-LSH11-172 | AS350 B3            | INTERIOR MODIFICATION            | 350-702274                               | 03-Oct-11 | 0    |
| ICA-ECL-237   | SH96-126    | AS350/355/<br>EC130 | BLADE TIE DOWN PROVISIONS        | 350-700414/<br>130-700414                | 12-May-15 | 2    |
| ICA-ECL-238   | O-LSH11-167 | AS350 B3            | INTERIOR MODIFICATION            | 350-702284                               | 26-Sep-11 | 0    |
| ICA-ECL-241   | O-LSH11-220 | EC130 B4            | INTERIOR MODIFICATION            | 130-701694                               | 08-Dec-11 | 0    |
| ICA-ECL-242   | SH12-28     | AS350 / 355         | STANDARD INTERIOR MODIFICATION   | 350-701904                               | 21-Mar-18 | 5    |
| ICA-ECL-243   | SH12-28     | AS350 / 355         | STANDARD INTERIOR MODIFICATION   | 350-701814                               | 11-Nov-14 | 2    |
| ICA-ECL-244   | SH12-28     | AS350 / 355         | STANDARD INTERIOR MODIFICATION   | 350-701074,<br>350-702104,<br>350-702124 | 21-Mar-18 | 3    |
| ICA-ECL-245   | SH12-28     | AS350 / 355         | STANDARD INTERIOR MODIFICATION   | 350-701044                               | 21-Mar-18 | 4    |
| ICA-ECL-246   | O-LSH12-010 | AS350 B3            | INTERIOR MODIFICATION            | 350-702314                               | 20-Jan-12 | 0    |

Instructions for Continued Airworthiness

Last updated: 9 November 2020



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>                   | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|---------------------------------------|--------------------|-------------|-------------|
| ICA-ECL-247          | O-LSH12-033/D     | AS350 B3     | INTERIOR MODIFICATION                 | 350-702294         | 09-Mar-12   | 0           |
| ICA-ECL-248          | O-LSH12-046       | AS350 B2     | INTERIOR MODIFICATION                 | 350-702334         | 08-Mar-12   | 1           |
| ICA-ECL-249          | O-LSH12-054       | AS350 B3     | INTERIOR MODIFICATION                 | 350-702304         | 21-Mar-12   | 1           |
| ICA-ECL-250          | SH12-12           | EC130        | REAR DRIVE SHAFT END CAP INSTALLATION | 130-300014         | 09-Jul-14   | 1           |
| ICA-ECL-251          | SH12-16           | AS350 B3     | OPERATION WITH SANDFILTER REMOVED     | 350-800044         | 13-Mar-12   | 2           |
| ICA-ECL-252          | O-LSH12-079       | AS350 B3     | INTERIOR MODIFICATION                 | 350-702324         | 24-Apr-12   | 0           |
| ICA-ECL-253          | O-LSH12-086       | AS350 B3     | INTERIOR MODIFICATION                 | 350-702354         | 14-May-12   | 1           |
| ICA-AHCA-254         | SH14-10           | AS350 B2, B3 | LONGLINE ELECTRICAL PROVISIONS        | 350-900564         | 29-Apr-15   | 3           |
| ICA-ECL-255          | O-LSH12-189       | AS350 B3     | COMM NAV SYSTEM                       | 350-881014         | 10-Dec-12   | 0           |
| ICA-ECL-256          | O-LSH12-096       | EC130 B4     | INTERIOR MODIFICATION                 | 130-701714         | 22-May-12   | 1           |
| ICA-ECL-257          | O-LSH12-099       | EC130 B4     | INTERIOR MODIFICATION                 | 130-701704         | 25-May-12   | 1           |
| ICA-ECL-258          | O-LSH12-126       | AS350 B3     | INTERIOR MODIFICATION                 | 350-702384         | 18-Jun-12   | 1           |



| Report Number | STC Number    | Model            | Report Title                     | Part Number | Date      | Rev. |
|---------------|---------------|------------------|----------------------------------|-------------|-----------|------|
| ICA-ECL-259   | SH12-28       | AS350 / 355      | STANDARD INTERIOR MODIFICATION   | 350-702204  | 11-Nov-14 | 2    |
| ICA-ECL-260   | SH96-39       | AS350 BA, B2, B3 | TWO PLACE FORWARD PASSENGER SEAT | 350-200624  | 18-Dec-13 | 2    |
| ICA-ECL-261   | O-LSH12-177   | AS350 B3e        | INTERIOR MODIFICATION            | 350-702364  | 01-Nov-12 | 1    |
| ICA-ECL-262   | O-LSH12-168/D | AS350 B2         | INTERIOR MODIFICATION            | 350-702344  | 31-Oct-12 | 0    |
| ICA-ECL-266   | O-LSH13-041   | AS350 B2         | INTERIOR MODIFICATION            | 350-702374  | 21-Mar-13 | 0    |
| ICA-ECL-267   | O-LSH13-038   | EC130 B4         | INTERIOR MODIFICATION            | 130-701724  | 15-Mar-13 | 1    |
| ICA-ECL-268   | O-LSH13-123   | EC135            | INTERIOR MODIFICATION            | 135-701624  | 29-Aug-13 | 0    |
| ICA-AHCA-269  | SH20-44       | EC130 T2         | AIRFRAME-MOUNTED FUEL FILTER     | 130-600204  | 28-Oct-20 | 1    |
| ICA-ECL-270   | SH14-11       | AS350 / EC130    | FIRE EXTINGUISHER RELOCATION     | 130-700014  | 28-Mar-14 | 1    |
| ICA-ECL-271   | O-LSH13-150   | EC120 B          | INTERIOR MODIFICATION            | 120-701664  | 21-Nov-13 | 1    |
| ICA-ECL-272   | O-LSH13-161   | EC135            | INTERIOR MODIFICATION            | 135-701634  | 12-Dec-13 | 1    |
| ICA-AHCA-273  | SH14-31       | EC130 T2         | CARGO PODS                       | 130-201214  | 04-Jul-18 | 1    |



| Report Number | STC Number              | Model        | Report Title                                        | Part Number   | Date      | Rev. |
|---------------|-------------------------|--------------|-----------------------------------------------------|---------------|-----------|------|
| ICA-AHCA-274  | SH14-40                 | EC130 T2     | CARGO MIRRORS                                       | 130-201414    | 19-Dec-14 | 3    |
| ICA-AHCA-275  | SH14-13                 | EC130B4 / T2 | STANDARD INTERIOR MODIFICATION                      | 130-701904    | 16-Apr-14 | 0    |
| ICA-AHCA-276  | SH14-13                 | EC130B4 / T2 | STANDARD INTERIOR MODIFICATION                      | 130-701814    | 16-Apr-14 | 0    |
| ICA-AHCA-277  | O-LSH14-072/D           | EC130 T2     | INTERIOR MODIFICATION                               | 130-701734    | 25-Jun-14 | 0    |
| ICA-AHCA-278  | SH14-20                 | EC135        | STANDARD INTERIOR MODIFICATION                      | 135-701644    | 26-May-14 | 0    |
| ICA-AHCA-279  | SH97-60                 | AS355        | CARGO PODS LH/RH INSTALLATION                       | 355-200814/24 | 18-Oct-19 | 1    |
| ICA-AHCA-280  | O-LSH14-148/D<br>SH15-2 | AS355 NP     | LEAD ACID BATTERY                                   | 355-700024    | 12-Jun-15 | 1    |
| ICA-AHCA-281  | O-LSH14-150/D           | AS355 NP     | LONGLINE CONTROL SYSTEM                             | 355-900034    | 12-Dec-14 | 0    |
| ICA-AHCA-282  | O-LSH14-147/D           | AS355 NP     | FLIGHT FOLLOWING SATPHONE                           | 355-903014    | 12-Dec-14 | 0    |
| ICA-AHCA-283  | O-LSH14-149/D           | AS355 NP     | PULSE LIGHT INSTALLATION                            | 355-902414    | 12-Dec-14 | 0    |
| ICA-AHCA-284  | O-LSH14-089/D           | AS350 B2     | INTERIOR MODIFICATION                               | 350-702394    | 08-Aug-14 | 0    |
| ICA-AHCA-286  | SH15-7                  | AS 355 N, NP | INSTALLATION OF HIGH VISIBILITY FORWARD CABIN DOORS | 350-202014    | 04-May-15 | 0    |



| Report Number | STC Number    | Model         | Report Title                                   | Part Number   | Date      | Rev. |
|---------------|---------------|---------------|------------------------------------------------|---------------|-----------|------|
| ICA-AHCA-287  | O-LSH14-138/D | AS355 NP      | COMM NAV SYSTEMS                               | 355-880054    | 12-Dec-14 | 0    |
| ICA-AHCA-288  | O-LSH14-120/D | EC130 B4      | INTERIOR MODIFICATION                          | 130-701754    | 25-Nov-14 | 0    |
| ICA-AHCA-289  | O-LSH15-011/D | EC130 T2      | INTERIOR MODIFICATION                          | 130-701744    | 06-Mar-15 | 0    |
| ICA-AHCA-290  | O-LSH15-022   | AS350         | FIRE EXTINGUISHER RELOCATION                   | 350-702074    | 13-Mar-15 | 0    |
| ICA-AHCA-291  | O-LSH15-032/D | EC130 T2      | INTERIOR MODIFICATION                          | 130-701824    | 12-May-15 | 0    |
| ICA-AHCA-292  | SH15-48       | EC130 T2      | 50 AMP / LONGLINE / CAROUSEL SYSTEM            | 130-900024    | 23-Oct-15 | 0    |
| ICA-AHCA-293  | O-LSH15-112/D | EC130 T2      | GARMIN G500H DEVATIONS TO FAA STC SR09497RC-D  | 130-950304    | 06-Oct-15 | 0    |
| ICA-AHCA-294  | SH97-15       | AS 350        | INSTALLATION OF LH and/or RH CARGO PODS        | 350-201814/24 | 03-Feb-17 | 1    |
| ICA-AHCA-295  | SH16-14       | EC135         | REMOVEABLE DOOR PINS                           | 135-201014    | 11-Mar-16 | 0    |
| ICA-AHCA-296  | SH16-11       | AS350 / EC130 | PROVISIONS, ENGINE AIR INTAKE COVER            | 350-700924    | 04-Mar-16 | 0    |
| ICA-AHCA-298  | SH17-47       | BK117 C-2/D-2 | INSTALLATION OF REMOVABLE PINS FOR HINGED DOOR | 145-201014    | 08-Dec-17 | 0    |
| ICA-AHCA-299  | O-LSH19-060/D | EC 130 T2     | HEAVY DUTY BATTERY INSTALLATION                | 130-700244    | 06-Jun-19 | 1    |

Instructions for Continued Airworthiness

Last updated: 9 November 2020





| Report Number | STC Number    | Model                    | Report Title                                           | Part Number | Date      | Rev. |
|---------------|---------------|--------------------------|--------------------------------------------------------|-------------|-----------|------|
| ICA-AHCA-300  | O-LSH18-051   | AS 350 B3                | SEAT COVERS MODIFICATIONS                              | 350-702444  | 19-Apr-19 | 0    |
| ICA-AHCA-302  | O-LSH18-077/D | AS 350 B3                | SEAT COVERS MODIFICATIONS                              | 350-702454  | 11-Jun-18 | 0    |
| ICA-AHCA-303  | SH18-56       | AS 350 B3 /<br>EC 130 T2 | ALTERNATE STANDBY ALTIMETER                            | 350-957264  | 09-Oct-18 | 0    |
| ICA-AHCA-304  | O-LSH18-167   | BK 117 D-2               | FLOOR COVERS                                           | 145-701614  | 29-Nov-18 | 0    |
| ICA-AHCA-305  | SH18-67       | BK 117 D-2               | MICROWAVE DOWNLINK SYSTEM                              | 145-902714  | 28-Nov-18 | 0    |
| ICA-AHCA-306  | O-LSH18-170   | BK 117 D-2               | SEAT COVERS MODIFICATIONS                              | 145-701634  | 11-Dec-18 | 0    |
| ICA-AHCA-307  | O-LSH19-061/D | EC 130 T2                | GARMIN GTS-800 TRAFFIC ADVISORY SYSTEM<br>INSTALLATION | 130-870514  | 06-Jun-19 | 1    |
| ICA-AHCA-308  | O-LSH19-065/D | EC 130 T2                | INTERIOR MODIFICATIONS                                 | 130-701784  | 04-Apr-18 | 0    |
| ICA-AHCA-310  | SH19-56       | EC 130 T2                | HEAVY DUTY BATTERY INSTALLATION                        | 130-700244  | 16-Dec-19 | 0    |
| ICA-AHCA-311  | SH19-32       | BK117 D-2                | SUPPLEMENTAL CABIN HEATER INSTALLATION                 | 145-900004  | 20-Sep-19 | 0    |
| ICA-AHCA-313  | O-LSH19-194/D | AS 350 B3                | SEAT COVERS MODIFICATIONS                              | 350-702474  | 20-Dec-19 | 0    |