



| Report Number | STC Number   | Model            | Report Title                        | Part Number                 | Date      | Rev.                               |
|---------------|--------------|------------------|-------------------------------------|-----------------------------|-----------|------------------------------------|
| MMS-ECL-003   |              | AS350 BA, B2, B3 | AIRFRAME FUEL FILTER                | 350-600004                  |           | <b>Superseded with ICA-ECL-130</b> |
| MMS-ECL-006   | SH96-31      | AS355            | BATTERY POWER SYSTEM RELOCATION     | 350-700214/324              |           | <b>Superseded with ICA-ECL-125</b> |
| MMS-ECL-023   |              | AS350/355        | SETTLING PROTECTORS                 | 350-500214                  |           | <b>Superseded with ICA-ECL-124</b> |
| MMS-ECL-024   |              | AS350/355        | AIRBORNE SATELLITE TELEPHONE SYSTEM | 350-901704                  | 24-May-00 | 1                                  |
| MMS-ECL-028   | SH96-129     | AS350/355        | STIRRUP STEPS INSTALLATION          | 350-201604                  | 19-Apr-00 | 0                                  |
| MMS-ECL-029   | SH98-44      | AS350/355        | RAIL STEPS                          | 350-500194/204              | 11-Jul-00 | 0                                  |
| MMS-ECL-032   |              | AS350            | PA / SIREN SYSTEM                   | 350-888594                  | 27-Jul-00 | 0                                  |
| MMS-ECL-033   | SH97-36      | AS350            | COWLING MAINTENANCE STEPS           | 350-200094/104              | 26-May-00 | 0                                  |
| MMS-ECL-035   | SH00-1       | AS350            | HIGH VISIBILITY DOOR                | 350-202014                  | 30-Aug-04 | 2                                  |
| MMS-ECL-036   |              | AS350            | LEFT SIDE PILOT CONFIGURATION       | 350-400004/74<br>350-400164 |           | <b>Superseded with ICA-ECL-168</b> |
| MMS-ECL-037   |              | AS350/355        | SETTLING PROTECTORS                 | 120-500214                  |           | <b>Superseded with ICA-ECL-026</b> |
| MMS-ECL-040   | SH96-115     | AS350            | FIREWALL REINFORCEMENT              | 350-601014                  | 30-Aug-04 | 1                                  |
| MMS-ECL-101   | O-LSH04-078  | AS350 B3         | MISSION EQUIPMENT MODIFICATIONS     | 350-902804/904              | 24-May-12 | 5                                  |
| MMS-ECL-102   | O-LSH08-186D | AS350 B3         | FLIR U8000/U8500 SYSTEM             | 350-903544                  | 28-Aug-08 | 0                                  |
| MMS-ECL-103   | O-LSH07-049D | AS350 B3         | AUTOPILOT INTERFACE                 | 350-401144                  | 28-Aug-08 | 0                                  |
| MMS-ECL-104   | O-LSH08-188D | AS350 B3         | COMM NAV                            | 350-880914                  | 28-Aug-08 | 0                                  |



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>   | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|-----------------------|--------------------|-------------|-------------|
| MMS-ECL-105          | O-LSH08-187D      | AS350 B3     | VIDEO DOWNLINK SYSTEM | 350-902934         | 28-Aug-08   | 0           |
| MMS-ECL-106          | O-LSH09-200D      | AS350 B3     | VIDEO DOWNLINK SYSTEM | 350-902974         | 22-Jun-09   | 0           |
| MMS-ECL-107          |                   | AS350 B3     | VIDEO DOWNLINK SYSTEM | 350-902984         | 03-Jul-09   | 0           |
| MMS-ECL-108          | O-LSH07-051D      | AS350 B3     | FLIR U8500            | 350-903584         | 22-Jun-09   | 0           |