



| Report Number | STC Number | Model            | Report Title                                 | Part Number              | Date                               | Rev. |
|---------------|------------|------------------|--|--------------------------|------------------------------------|------|
| PG-ECL-100    | N/A        | AS350 BA, B2, B3 | LONGLINE WITH 50 AMP POWER SYSTEM (STANDARD) | 350-900514               | 08-Jun-04                          | 2    |
| PG-ECL-101    | N/A        | AS350            | PUBLIC ADDRESS / SIREN SYSTEM                |                          | 03-Mar-03                          | 0    |
| PG-ECL-102    | N/A        | AS350 B3         | RIGHT HAND LITTER KIT INSTALLATION           | 350-200144               | <b>Superseded with FMS-ECL-108</b> |      |
| PG-ECL-103    | N/A        | EC130 B4         | LONGLINE WITH 50 AMP POWER SYSTEM            | 130-900014               | 07-Jul-08                          | 2    |
| PG-ECL-104    | N/A        | EC130 B4 / T2    | DOOR OPEN WARNING                            | 130-900104<br>130-900114 | 12-May-15                          | 1    |
| PG-ECL-105    | N/A        | EC120 B          | LONGLINE WITH 50 AMP POWER.                  | 120-922034               | 29-Jan-05                          | 0    |
| PG-ECL-106    | N/A        | AS355 N          | LONGLINE WITH 50 AMP POWER SYSTEM            | ESK-1353                 | 11-May-06                          | 0    |
| PG-ECL-107    | N/A        | AS350 B2, B3     | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554               | 22-May-07                          | 0    |
| PG-ECL-108    | N/A        | AS350 B2         | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554 (SN Specific) | 03-Aug-07                          | 0    |
| PG-ECL-109    | N/A        | EC120            | LONGLINE WITH 50 AMP POWER SYSTEM            | 120-922034               | 03-Dec-09                          | 1    |
| PG-ECL-110    | N/A        | AS350            | DOOR OPEN WARNING                            | 350-900274               | 26-Feb-08                          | 0    |
| PG-ECL-111    | N/A        | AS355 NP         | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554 (SN Specific) | 08-Aug-08                          | 0    |
| PG-ECL-112    | N/A        | AS355 NP         | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900554 (SN Specific) | 07-Feb-11                          | 0    |
| PG-ECL-113    | N/A        | AS350 B2, B3     | LONGLINE WITH 50 AMP POWER SYSTEM            | 350-900564               | 20-Jan-12                          | 0    |

Pilot's Guides

Last Updated: 5 September 2017



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>               | <b>Part Number</b>          | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|-----------------------------------|-----------------------------|-------------|-------------|
| PG-ECL-114           | N/A               | AS350 B3     | LONGLINE WITH 50 AMP POWER SYSTEM | 350-900954<br>(SN Specific) | 30-May-13   | 0           |