



| Report Number | STC Number        | Model        | Report Title                          | Part Number                      | Date        | Rev. |
|---------------|-------------------|--------------|---------------------------------------|----------------------------------|-------------|------|
| FMS-ECL-003   | SH94-31           | AS350 B,BA   | AIRFRAME-MOUNTED FUEL FILTER          | 350-600004                       | 15-May-07   | 4    |
| FMS-ECL-004   | SH94-31           | AS350 B1, B2 | AIRFRAME-MOUNTED FUEL FILTER          | 350-600004                       | 15-May-07   | 4    |
| FMS-ECL-007   | SH96-32           | AS350 BA, B2 | LEFT SIDE PILOT CONFIRGURATION        | 350-400004                       | 25-Oct-2013 | 8    |
| FMS-ECL-008   | SH96-39           | AS350        | TWO PLACE FORWARD PASSENGER SEAT (RH) | 350-200624                       | 05-Nov-12   | 6    |
| FMS-ECL-009   | SH97-15 / SH97-60 | AS350/355    | LH AND/OR RH CARGO PODS INSTALLATION  | 350-200814/824<br>355-200814/824 | 02-Mar-15   | 4    |
| FMS-ECL-010   | SH96-113          | AS350/355    | AFT CABIN DOORS REMOVED               |                                  | 09-Aug-00   | 1    |
| FMS-ECL-015   | SH02-42           | AS350 B3     | AIRFRAME-MOUNTED FUEL FILTER          | 350-600024                       | 19-Dec-12   | 7    |
| FMS-ECL-016A  | O-LSH98-344       | EC120 B      | NAVIGATION DISPLAY                    |                                  | 21-Dec-99   | 0    |
| FMS-ECL-019   | SH96-32           | AS350 B3     | LEFT SIDE PILOT CONFIGURATION         | 350-400074                       | 25-May-10   | 5    |
| FMS-ECL-022A  | O-LSH99-078       | EC120 B      | NAVIGATIONAL DISPLAY                  |                                  | 16-Apr-99   | 0    |
| FMS-ECL-027B  | O-LSH01-065       | AS350 B      | NAVIGATION DISPLAY                    |                                  | 15-Aug-01   | 0    |
| FMS-ECL-028A  | O-LSH00-017       | AS350 B3     | AUTOPILOT HEADING SUB MODE            |                                  | 04-Oct-00   | 0    |
| FMS-ECL-028B  | O-LSH01-056       | AS350 B      | AUTOPILOT HEADING SUB MODE            |                                  | 15-Aug-01   | 0    |



| Report Number | STC Number    | Model    | Report Title  | Part Number | Date      | Rev. |
|---------------|---------------|----------|---|-------------|-----------|------|
| FMS-ECL-031C  | O-LSH01-028   | EC120 B  | NAVIGATION DISPLAY (S/M 1136)   |             | 15-Aug-01 | 0    |
| FMS-ECL-032A  | O-LSH01-087   | EC120 B  | FLIR 445G MARK 2 SYSTEM   |             | 11-Dec-01 | 2    |
| FMS-ECL-035A  | O-LSH00-096   | AS350 B2 | FLOOR MOUNTED TORQUE METER  |             | 17-May-00 | 0    |
| FMS-ECL-037   | SH96-32       | AS350 B3 | LEFT SIDE PILOT CONFIGURATION   | 350-400164  | 05-Nov-12 | 5    |
| FMS-ECL-038A  |               | EC120 B  | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-038B  |               | EC120 B  | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM                     |             | 27-Jun-01 | 0    |
| FMS-ECL-038C  |               | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-038D  |               | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-100A  | O-LSH02-6721D | EC120 B  | FLIR SYSTEM   |             | 20-Nov-02 | 0    |
| FMS-ECL-101   |               | EC120 B  | SX-16 SEARCHLIGHT INSTALLATION  |             | 20-Nov-02 | 0    |
| FMS-ECL-102   | SH02-39       | EC120 B  | IMPROVED HEATING SYSTEM   | 120-701014  | 19-Oct-10 | 4    |
| FMS-ECL-103   | SH02-42       | EC130 B4 | AIRFRAME-MOUNTED FUEL FILTER  | 130-600004  | 10-Apr-08 | 5    |
| FMS-ECL-105   | SH02-45       | EC130 B4 | LITTER KIT  | 130-200034  | 28-Nov-07 | 1    |
| FMS-ECL-106   | O-LSH03-70    | AS350 B3 | OPERATION WITH LEFT HAND PILOT DOOR REMOVED                           |             | 01-Apr-03 | 0    |



| Report Number | STC Number   | Model            | Report Title   | Part Number    | Date      | Rev. |
|---------------|--------------|------------------|--|----------------|-----------|------|
| FMS-ECL-107   | SH94-29      | AS350/355        | LEFT HAND LITTER KIT   | 350-200034     | 11-Dec-06 | 5    |
| FMS-ECL-108   | SH96-62      | AS350 BA, B2, B3 | RIGHT HAND LITTER KIT  | 350-200144     | 15-Dec-08 | 4    |
| FMS-ECL-109   | SH03-15      | EC120 B          | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER MOUNT (W/OUT PILOT'S CYCLIC CONTROL) | 120-901234     | 09-Nov-05 | 1    |
| FMS-ECL-110   | SH03-15      | EC120 B          | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER MOUNT (WITH PILOT'S CYCLIC CONTROL)  | 120-901234     | 09-Nov-05 | 1    |
| FMS-ECL-111   | O-LSH03-207  | AS350 B3         | AUTOPILOT HEADING SUB-MODE   | 350-401124     | 25-Mar-04 | 1    |
| FMS-ECL-112   | SH04-53      | EC130 B4         | OPERATION WITH SANDFILTER REMOVED  | 130-800034     | 30-Nov-04 | 0    |
| FMS-ECL-114   | SH03-15      | EC120 B          | SX-16 SEARCHLIGHT INSTALLATION WITH SLASS                                  | 120-901234     | 09-Nov-05 | 0    |
| FMS-ECL-115   | SH05-47      | EC 120 B         | FLIR U8500/U8500 SYSTEM INSTALLATION                                       | 120-901814     | 04-Dec-08 | 1    |
| FMS-ECL-116   | O-LSH05-310  | EC120 B          | VIDEO DOWNLINK SYSTEM  | 120-902904     | 19-May-06 | 1    |
| FMS-ECL-117   | SH06-12      | AS350/355        | ENLARGED VERTICAL REFERENCE WINDOW   | 350/355-201154 | 28-Jan-15 | 4    |
| FMS-ECL-118   | O-LSH06-309  | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8                                     | 120-880204     | 18-Apr-07 | 3    |
| FMS-ECL-119   | O-LSH06-329  | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8                                     | 120-880204     | 16-Apr-07 | 2    |
| FMS-ECL-120   | O-LSH06-337  | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM & AUTOPILOT                                | 120-880214     | 05-Apr-07 | 3    |
| FMS-ECL-121   | O-LSH07-050D | AS350 B3         | VIDEO DOWNLINK SYSTEM  | 350-902924     | 20-Feb-06 | 0    |



| Report Number | STC Number    | Model    | Report Title                                | Part Number | Date      | Rev. |
|---------------|---------------|----------|---|-------------|-----------|------|
| FMS-ECL-122   | O-LSH07-0491D | AS350 B3 | AUTOPILOT HEADING SUBMODE                   | 350-401144  | 28-Aug-08 | 1    |
| FMS-ECL-126   | O-LSH08-187D  | AS350    | VIDEO DOWNLINK SYSTEM                       | 350-902934  | 28-Aug-08 | 0    |
| FMS-ECL-127   | O-LSH08-282D  | EC120 B  | VIDEO DOWNLINK SYSTEM (STRATA DIGITAL)      | 120-902934  | 12-Dec-08 | 0    |
| FMS-ECL-128   | O-LSH08-288   | AS350 B3 | COMM NAV SYSTEM                             |             | 20-Jul-10 | 5    |
| FMS-ECL-129   | O-LSH08-288   | AS350 B3 | TWO PLACE FORWARD PASSENGER SEAT            | 350-200624  | 19-Dec-08 | 0    |
| FMS-ECL-130   | O-LSH08-288   | AS350 B3 | LH PILOT CONFIGURATION                      | 350-400164  | 19-Dec-08 | 0    |
| FMS-ECL-131   |               | EC120 B  | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880204  | 09-Jan-13 | 0    |
| FMS-ECL-132   |               | EC120 B  | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880214  | 09-Jan-13 | 0    |
| FMS-ECL-133   | SH09-11       | AS350 B2 | DUAL SAGEM ICDS-6A INSTALLATION             | 350-873044  | 21-Apr-09 | 0    |
| FMS-ECL-134   | O-LSH09-245   | EC120 B  | DUAL SAGEM ICDS-6A                          | 120-872744  | 11-Aug-09 | 3    |
| FMS-ECL-135   | O-LSH09-200D  | AS350 B3 | VIDEO DOWNLINK SYSTEM                       | 350-902974  | 22-Jun-09 | 0    |
| FMS-ECL-136   | O-LSH09-210D  | AS350 B3 | VIDEO DOWNLINK SYSTEM                       | 350-902984  | 03-Jul-09 | 0    |
| FMS-ECL-137   | SH10-20       | EC130 B4 | OPERATION WITH DOORS REMOVED                |             | 18-Dec-13 | 2    |
| FMS-ECL-138   | O-LSH10-308   | EC120 B  | FLIR U8500 SYSTEM INSTALLATION              | 120-901864  | 30-Nov-10 | 1    |



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>               | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|-----------------------------------|--------------------|-------------|-------------|
| FMS-ECL-139          | O-LSH11-066       | EC135        | FLIR INSTALLATION                 | 135-901814         | 21-Apr-11   | 0           |
| FMS-ECL-140          | O-LSH11-065       | EC135        | SX-16 INSTALLATION                | 135-901214         | 21-Apr-11   | 0           |
| FMS-ECL-141          | O-LSH11-070       | EC135        | VIDEO DOWNLINK                    | 135-902714         | 15-Apr-11   | 0           |
| FMS-ECL-142          | O-LSH11-069       | EC135        | DOOR OPEN WARNING                 | 135-901014         | 15-Apr-11   | 0           |
| FMS-ECL-143          | O-LSH11-073/D     | AS350 B2     | COMM NAV SYSTEM                   | 350-880974         | 20-Apr-11   | 1           |
| FMS-ECL-144          | O-LSH11-068       | EC135        | CARGO COMPARTMENT MODS            | 135-200304         | 13-Apr-11   | 0           |
| FMS-ECL-145          | O-LSH11-0081/D    | AS350 B3     | BMS DOWNLINK                      | 350-902994         | 10-May-11   | 1           |
| FMS-ECL-146          | O-LSH11-074/D     | EC135        | PULSE LIGHT INSTALLATION          | 135-902414         | 18-Apr-11   | 0           |
| FMS-ECL-148          | SH11-35           | EC130 B4     | ADJUSTABLE GLARE SHIELD           | 130-885114         | 20-Sep-11   | 0           |
| FMS-ECL-149          | O-LSH11-111       | AS350 B3     | ADJUSTABLE GLARE SHIELD           | ESK-1457           | 17-Jun-11   | 0           |
| FMS-ECL-151          | SH12-16           | AS350 B3     | OPERATION WITH SANDFILTER REMOVED | 350-800044         | 13-Mar-12   | 2           |
| FMS-ECL-153          | O-LSH12-189       | AS350 B3     | COMM NAV SYSTEM                   | 350-881014         | 10-Dec-12   | 0           |
| FMS-AHCA-152         | SH14-10           | AS350 B2, B3 | LONG LINE ELECTRICAL PROVISIONS   | 350-900564         | 29-Apr-15   | 3           |
| FMS-ECL-154          | SH02-42           | AS350 B3     | AIRFRAME-MOUNTED FUEL FILTER      | 350-600024         | 21-Dec-12   | 2           |



| <b>Report Number</b> | <b>STC Number</b> | <b>Model</b> | <b>Report Title</b>                                 | <b>Part Number</b> | <b>Date</b> | <b>Rev.</b> |
|----------------------|-------------------|--------------|---|--------------------|-------------|-------------|
| FMS-ECL-155          | SH96-31           | AS350/355    | BATTERY RELOCATION                                  | 350-700324         | 03-Jul-13   | 1           |
| FMS-AHCA-159         | O-LSH14-148/D     | AS355 NP     | LEAD ACID BATTERY INSTALLATION                      | 355-700024         | 12-Dec-14   | 0           |
| FMS-AHCA-160         | O-LSH14-150/D     | AS355 NP     | 50 AMP / LONGLINE / CAROUSEL                        | 355-900034         | 12-Dec-14   | 0           |
| FMS-AHCA-161         | O-LSH14-147/D     | AS355 NP     | FLIGHT FOLLOWING SATPHONE                           | 355-903014         | 12-Dec-14   | 0           |
| FMS-AHCA-162         | O-LSH14-149/D     | AS355 NP     | PULSE LIGHT INSTALLATION                            | 355-902414         | 12-Dec-14   | 0           |
| FMS-AHCA-164         | O-LSH14-138/D     | AS355 NP     | COMM NAV SYSTEM                                     | 355-880054         | 12-Dec-14   | 0           |
| FMS-AHCA-165         | SH15-7            | AS 355 N, NP | INSTALLATION OF HIGH VISIBILITY FORWARD CABIN DOORS | 350-202014         | 04-May-15   | 1           |
| FMS-AHCA-166         | SH12-52           | AS355        | CABLE CUTTER INSTALLATION                           | 350-252004         | 19-Feb-15   | 0           |