

Transports Canada

Department of Transport

Supplemental Type Certificate

This approval is issued to:

Number: SH02-42

Airbus Helicopters Canada Limited

Issue No.:

1100 Gilmore Road

Approval Date:

P.O. Box 250

December 17, 2002

Fort Erie, Ontario Canada L2A 5M9 Issue Date: August 07, 2015

Responsible Office:

Ontario

Aircraft/Engine Type or Model:

Airbus Helicopters AS 350 B3, EC 130 B4

Canadian Type Certificate or Equivalent:

H-83 (Airbus Helicopters AS 350 B3, EC 130 B4)

Description of Type Design Change:

Airframe Mounted Fuel Filter Installation

(130-600004, 350-600024)

Installation/Operating Data, Required Equipment and Limitations:

> Configuration must be in accordance with the following Eurocopter Canada Limited Master Drawing Lists, or later TCCA approved revisions:

A/C Model	Master Drawing List No	Issue	TCCA Approval Date
EC130B4	MDL-02-001	G	26 June, 2007
AS350B3	MDL-04-005	F	19 December, 2012

(See Continuation Sheet)

Conditions: This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this modification, the installer shall establish that the interrelationship between this change and any other modification(s) incorporated will not adversely affect the airworthiness of the modified product.



For Minister of Transport



(Continuation Sheet)

Number: SH02-42 Issue 8

NOTE: THIS ADDENDUM SHALL REMAIN PART OF THE CERTIFICATE REFERRED TO THEREIN.

2. Installation must be in accordance with the following Eurocopter Canada Limited Installation Procedures, or later TCCA approved revisions:

A/C Model	Installation Procedure No	Revision	TCCA Approval Date
EC130B4	IP-ECL-105	6	26 June, 2007
AS350B3	IP-ECL-111	4	19 December, 2012

3. Operation must be in accordance with the following Eurocopter Canada Limited Flight Manual Supplements, or later TCCA approved revisions:

A/C Model	Flight Manual Supplement No	Revision	TCCA Approval Date
EC130B4	FMS-ECL-103	6	12 June, 2015
AS350B3 (pre mod 4305)	FMS-ECL-15	. 8	12 June, 2015
AS350B3 (post mod 4305)	FMS-ECL-154	3	12 June, 2015

4. The rotorcraft must be maintained in accordance with the following Eurocopter Canada Instructions for Continued Airworthiness, or later TCCA accepted revisions:

A/C Model	Instructions for Continued Airworthiness No	Revision	TCCA Acceptance Date
EC130B4	ICA-ECL-118	9	21 July, 2015
AS350B3	ICA-ECL-129	7	21 July, 2015