

## STARFLEX REPAIR SERVICE



Airbus Helicopters Canada continuously strives to provide improved support & services for our customers.

The introduction of the Starflex Repair Service is another step in the improvment of our customer service offers.

If debonding of the Starflex bushings is detected (refer to SIN 2481-S-62), your Starflex may be repairable.

This service is currently available for Part Number – 350A31-1917-00 & -01 as well as, 350A31-1918-00.

### **REPAIR PROCESS**


There are four steps to the repair solution:

#### A. Visual & Dimensional Inspection:

An inspection is conducted to determine if the Starflex is repair worthy. If the part qualifies, the repair is launched.







### **CONTACT INFORMATION**

#### Manager, Commercial Office

Amanda Bondar Tel: (905) 994-2974 amanda.bondar@eurocopter.ca

# Customer Service Representative Bill Reid

Tel: (604) 244-1669 bill.reid@eurocopter.ca

### Customer Service Representative

Tracey Lahaie Tel: (905) 994-2957 tracey.lahaie@eurocopter.ca

#### Customer Service Representative Dan Payette Tel: (514) 334-5554

dan.payette@eurocopter.ca

# Customer Service Representative Candace Dandridge

Tel: (604) 244-1669 candace.dandridge@eurocopter.ca

#### Customer Service Representative

Max Dobbie Tel: (905) 994-2954 max.dobbie@eurocopter.ca

#### Customer Service Representative Ruby Smith Tel: (905) 994-2930 ruby.smith@eurocopter.ca





Starflex Repair criteria created by Airbus Helicopters

Thinking without limits, Starflex Repair Services are trademarks of the Airbus Helicopters Group. Corporate Communications Department. Airbus Helicopters reserves the right to make changes at any time without notice. The facts and figures contained in this document and expressed in good faith do not constitute any offer or contract with Airbus Helicopters.